



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2101743

INV Date 18/03/2021

Reference CC4/LPC20011362/T1pa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 3345D
Insured Veh. SLP 7480A
Claim No. 20/20/20/VP05/023779
Policy No. Z20VP05026913
Accident Date 16/10/2020
Inspection Date 20/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20011362/T1pa3q2 Date: 18/03/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 7480A	Veh. Inspected	SMJ 3345D	
Policy No.	Z20VP05026913	Coverage (\$)	0.00	
Claim No.	20/20/20/VP05/023779	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	20/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JF1SJ5KC5JG112568	Colour	SILVER	
Odometer	21732 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/10/2020	Inspection Date	20/10/2020	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 . SINGAPORE 319255			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 3345D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT FENDER LH (N)	BENT	270.00	270.00
1	BRKT CORNER F LH (N)	DISTORTED	36.00	36.00
1	BRKT SD F RH (N)	NOT NECESSARY	12.60	-
1	BRKT SD F LH (N)	DISTORTED	12.60	12.60
1	MOLDING BMPR F (N)	CUT	43.20	43.20
1	BUMPER FACE F NA (FOR H/L WSH) (N)	DEFORMED	594.00	594.00
1	BACK BEAM CPL F (N)	NOT NECESSARY	288.00	-
1	ENERGY ABSOR F (N)	BENT	126.00	126.00
1	COVER HOOK F STD (N)	NOT NECESSARY	4.40	-
1	MUD GUARD ASSY F LH (N)	DEFORMED	108.00	108.00
1	LAMP ASSY HEAD EOF LH (N)	CRACKED	2,380.00	2,380.00
1	TANK HLS (N)	CRACKED	93.60	93.60
1	NOZZLE H L WASHER LH (N)	MISSING	79.20	79.20
1	NOZZLE COVER ASSY LH (N)	NOT NECESSARY	54.00	-
1	WHEEL APR FF C RPLH (N) (ADDITIONAL)	DEFORMED	172.80	172.80
1	EXT FENDER F CP LH (N) (ADDITIONAL)	BENT	25.20	25.20
1	COVER FENDER UPR LH (N) (ADDITIONAL)	DEFORMED	18.00	18.00
1	CLIP GROMMET (N) (ADDITIONAL)	NECESSARY	3.60	3.60
1	CLIP BMPR (N) (ADDITIONAL)	NECESSARY	24.00	24.00
1	COWL PANEL SD LH (N) (ADDITIONAL)	DEFORMED	7.20	7.20
	LESS 20% DISCOUNT		-870.48	-798.68
			3,481.92	3,194.72
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) (ADDITIONAL)	NECESSARY	55.00	55.00
			55.00	55.00
	<u>LABOUR</u>			
	REMOVE & REFIX FRONT LHS FENDER INNER SUPPORT AND BRACE PANEL . (ADDITIONAL)		600.00	280.00
	REPAIR & JACK OUT BATTERY PANEL.(ADDITIONAL)		800.00	280.00
	SPRAY PAINT TO FRONT LHS FENDER INNER SUPPORT ,BRACE PANEL ,BATTERY PANEL.(ADDITIONAL)		1,320.00	880.00

Report Ref No. CC4/LPC20011362/T1pa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT 4 WHEEL ALIGNMENT.		171.00	171.00
	REMOVE /REPLACE FRONT BUMPER ASSY ,LHS FENDER .		2,320.00	1,120.00
	SPRAY PAINT FRONT BUMPER ASSY,BUMPER BEAM ,LHS FENDER .		1,440.00	880.00
	CONDUCT FRONT LIGHTING TEST.		150.00	150.00
	LTA INSPECTION FOR OPC -NUMBER PLATE .		120.00	120.00
	BALANCE TYRE.	NOT NECESSARY	28.00	-
			6,949.00	3,881.00
GRAND TOTAL			10,485.92	7,130.72
RECOMMENDED COST OF REPAIRS				7,130.72

Report Ref No. CC4/LPC20011362/T1pa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 3345D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 3345D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

