

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/096/2020
DATE : 19-OCT-2020

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : TAN SIANG EE
ADDRESS : APT BLK 343 YISHUN AVENUE 11
#12-137
S(760343)
TELEPHONE NO : 90938627

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPPHQ20-001439
VEHICLE NO : SMJ3345D
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YE50496
CHASSIS NO : JF1SJ5KC5JG112568
MILEAGE : 1 KM
DATE IN : 19/10/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 19/10/2020

Print Date : 19/10/2020
Print Time : 15:43:55

RIAL LIST FOR ACCIDENT VEHICLE REGN NO SMJ3345D

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS
1 FRT FENDER LH	57120SG0309P	270.00	bb✓		
2 BRKT CORNER F LH	57707SG010	36.00	dis✓		
3 BRKT SD F RH	57707SG020	12.60	x un		
4 BRKT SD F LH	57707SG030	12.60	dis✓		
5 MOLDING BMPR F	57708SG010	43.20	wt✓		
6 BUMPER FACE F NA (FOR H/L WSH)	57709SG030	594.00	de✓		
7 BACK BEAM CPL F	(SUPP) 57711SG0009P	288.00	X un		
8 ENERGY ABSOR F	(SUPP) 57722SG020	126.00	? ht✓		
9 COVER HOOK F STD	57731SG220	4.40	X un		
10 MUD GUARD ASSY F LH	59110SG031	108.00	de✓		
11 LAMP ASSY HEAD EOF LH	84002SG232	2380.00	inn✓		
12 TANK HLS (SUPP)	86631SG030	93.60	crn✓		
13 NOZZLE H L WASHER LH	(SUPP) 86636SG371	79.20	? mis✓		
14 NOZZLE COVER ASSYLH	86636SG390TQ	54.00	? X un		
SUB TOTAL		4101.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		820.32	0.00	0.00	0.00
GRAND TOTAL		3281.28	0.00	0.00	0.00
OVERALL TOTAL		3281.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMJ3345D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	1W0001W	TO CONDUCT 4-WHEEL ALIGNMENT	171.00	✓
2	ZZ/001	REMOVE/REPLACE FRONT BUMPER ASSY, LHS FENDER	560 2320.00	1120.
3	ZZ/002	SPRAY PAINT FRONT BUMPER ASSY, BUMPER BEAM, LHS FENDER	440 1440.00	880.
4	ZZ/003	CONDUCT FRONT LIGHTING TEST	150.00	✓
5	ZZ/004	LTA INSPECTION FOR OPC -NUMBER PLATE	120.00	✓
6	ZZ/005	BALANCE TYRE	28.00	X mm.
TOTAL LABOUR CHARGES			4229.00	

Taukhi 97495749 / 67418434
 'wp' 20/10/2020
 Resurvey before paint
 Taukhi @ 11hant.wm
 5 days 8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary (SMJ3345D // DOA: 16/10/2020)

Parts

WHEEL APR FF C RPLH	(SUPP) 51610SG1309P	172.80	de ✓	OK
EXT FENDER F CP LH	(SUPP) 57160SG0109P	25.20	bt ✓	OK
COVER FENDER UPR LH	(SUPP) 57256SG030	18.00	de ✓	OK
WHEEL APR FF C RPLH	(SUPP) 51610SG1309P	172.80	bt ✓	OK
WHEEL APR FF C RPLH	(SUPP) 51610SG1309P	172.80	mis ✓	OK
CLIP GROMMET	(SUPP) 909130013	3.60	nec ✓	OK
CLIP BMR	(SUPP) 909140007	24.00	nec ✓	OK
CONL PANEL SD LH	(SUPP) 91423SG010	7.20	de ✓	OK

Labour

ZZ/006	SUPPLEMENTARY JOB - FRONT NUMBER PLATE	55.00	55.00	nec ✓
ZZ/007	SUPPLEMENTARY JOB - REMOVE & REFIX FRONT LHS FENDER INNER SUPPORT AND BRACE PANEL	600.00	280.00	✓
ZZ/008	REPAIR & JACK OUT BATTERY PANEL	800.00	280.00	✓
ZZ/009	SPRAY PAINT TO FRONT LHS FENDER INNER SUPPORT, BRACE PANEL, BATTERY PANEL	1320.00	880.00	✓