

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0784/2020/NS
DATE : 19-Oct-20
WTP : 53636

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS LIM JIN MIN
ADDRESS : BLK 394 TAMPINES AVE 7
#06-265
SINGAPORE 520394
TELEPHONE : HP +65 98808578
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070111152
VEHICLE NO : SCW 999 L
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 24/7/2020
ENGINE NO : DEM 023855
CHASSIS NO : WAUZZZF4XLN013645
MILEAGE : 3800KM
DATE IN : 19-Oct-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Oct-20
PLACE OF ACCIDENT : LOYANG(JUNCTION OF DRIVE AND AVE)

\$17539.88

11 Days.

Veron.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCW 999 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	✓✓
	TO RENEW 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00	✓✓
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00	✓✓
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00 150	✓✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	✓✓
SUB TOTAL LABOUR CHARGES		: <u>\$ 2,960.00</u>	

PREMIUM AUTOMOBILES



55 HBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCW 999 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	✓ ✓
	TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	3000 ✓
7	TO RESPRAY REAR BUMPER, LHS REAR FENDER, DOOR ENTRANCES, LHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 5,000.00	3475 2475 ✓
8	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 14,732.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCW 999 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 REAR BUMPER <i>Deland</i>	\$	2,122.00	✓ 1697.60
2 REAR BUMPER FIXING PARTS <i>the m</i>	\$	164.00	+
3 REAR BUMPER SPOILER the m ✓ cut	\$	246.00	+ 196.40
4 REAR BUMPER BRACKET - LH <i>the m</i>	\$	201.00	+
5 REAR LIGHT REFLECTOR - LH INNER/OUTER <i>new</i>	\$	86.00	+
6 LED TAIL LIGHT - LH <i>2 Cut</i>	\$	1,008.00	✓ 806.40
7 TAIL LIGHT TRIM - LH the m <i>the m</i>	\$	30.00	+
8 EXHAUST TAIL PIPE TRIM - LH	\$	350.00	+
9 REAR BUMPER GUIDE SECTION - INNER <i>the m</i>	\$	44.00	+
10 REAR BUMPER GUIDE SECTION - OUTER <i>Damaged</i>	\$	22.00	✓ 17.52
11 REAR FENDER - LH <i>Dented</i>	\$	2,644.00	✓ 2115.20
12 REAR WINDSCREEN <i>the m</i>	\$	1,141.00	✓ 912.80
13 SIDE WINDOW - LH	\$	648.00	✓ 518.40
14 PRIMER <i>the m</i>	\$	19.00	✓ 14.96
15 REAR WHEEL HOUSING LINER - LH <i>the m</i>	\$	237.00	+
16 WHEEL HOUSING LINER ATTACHMENT PARTS <i>the m</i>	\$	138.00	+
17 REAR ALUMINIUM RIM - LH <i>the m</i>	\$	692.00	+
18 1/4 GLASS SEALANT <i>2</i>	S/N	100.00	✓ 100
19 REAR WINDSCREEN SEALANT <i>the m</i>	S/N	200.00	✓ 200
20 METAL FILLER POWDER	S/N	280.00	✓ 280
SUB TOTAL SPARE PARTS	:	\$ 10,372.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCW 999 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 STONE CHIP	2	S 180.00	✓ 180
22 CAVITY WAX	Na	S 140.00	✓ 140
23 ACRYLIC SEALANT		S 180.00	✓ 180
24 SUNDRIES	? ✓ Nec.	S 300.00	? 27.60
TOTAL SPARE PARTS	:	\$ 11,172.00	
TOTAL LABOUR CHARGES	:	\$ 14,732.00	
GRAND TOTAL	:	\$ 25,904.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lij
SURVEYED DATE : 20/10/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 12 Pairs.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT