

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 7340 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00	x
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	1000 2250
5	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$ 2,500.00	1100
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,052.00	

Resurveyed
09/11/20
H. L. Adrian Lj

Car-in Wip: Kiam / Hong

53507

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



AZK - Adm'm

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 7340 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>Replaced</i>		\$ 1,854.00	✓
2 FRONT BUMPER FIXING PARTS <i>new</i>		\$ 343.00	✓
3 FRONT BUMPER GRILLE - CENTRE <i>Replaced</i>		\$ 195.00	✓
4 FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Replaced</i>		\$ 334.00	167
5 FRONT BUMPER END CAP - LH / RH <i>new</i>	2	\$ 68.00	✓
6 FRONT BUMPER SPOILER <i>Replaced</i>		\$ 296.00	✓
7 FRONT BUMPER CLOSING ELEMENT <i>new</i>		\$ 154.00	✓
8 WHEEL SPOILER - LH / RH <i>new</i>	2	\$ 68.00	✓
9 FRONT BUMPER ADAPTER - RH ?		\$ 42.00	?
10 RADIATOR GRILLE <i>Conced</i>		\$ 1,395.00	✓
11 RADIATOR GRILLE STRIKER PLATE <i>Replaced</i>		\$ 123.00	✓
12 FRONT BUMPER FOAM FILLER PIECE <i>Replaced</i>		\$ 77.00	✓
13 FRONT BUMPER CARRIER <i>Replaced</i>		\$ 679.00	✓
14 FRONT BUMPER TOP COVER <i>Replaced</i>		\$ 99.00	✓
15 FRONT BUMPER GUIDE SECTION - RH ?		\$ 35.00	?
16 CAUTION SIGN STICKER ?	NEC	\$ 14.00	✓
17 AIRCON STICKER <i>new</i>	NEC	\$ 8.00	✓
18 SIGNAL HORN - RH HIGH TONE ?		\$ 180.00	?
19 SPRING SHACKLE - RH ?		\$ 31.00	?
20 BONNET <i>Dented</i>		\$ 2,757.00	✓
SUB TOTAL SPARE PARTS	:	\$ 8,752.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 7340 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 BONNET ATTACHMENT PARTS		\$ 163.00	+
22 BONNET LID HINGE - LH / RH	2	\$ 122.00	+
23 BONNET STRIKER - LH / RH	2	\$ 218.00	+
24 BONNET SOUND ABSORBER		\$ 217.00	+
25 BONNET IMPACT PROTECTION - CENTRE / LH / RH	3	\$ 90.00	✓
26 FRONT FENDER INNER COVER - LH / RH	2	\$ 32.00	+
27 PLENUM CHAMBER COVER		\$ 156.00	+
28 BONNET BOWDEN CABLE - CENTRE		\$ 57.00	+
29 BONNET RELEASE ELEMENT		\$ 57.00	+
30 BONNET LID LOCK	2	\$ 423.00	+
31 HEADLIGHT MOUNTING - LH / RH	2	\$ 234.00	117.
32 LED HEADLIGHT - LH / RH	2	\$ 9,718.00	+
33 LIFT CYLINDER - LH / RH	2	\$ 282.00	+
34 LIFT CYLINDER HOSE		\$ 175.00	+
35 RADIATOR AIR GUIDE - LH / RH	2	\$ 60.00	30
36 RADIATOR AIR GUIDE - UPPER CENTRE		\$ 22.00	✓
37 LOCK CARRIER		\$ 983.00	✓
38 READY MIX COOLANT		\$ 91.00	+
39 AIRCON CONDENSER		\$ 545.00	✓
40 FRONT WHEEL COVER - LH / RH	2	\$ 636.00	✓
41 FRONT NO PLATE	S/N	\$ 60.00	✓
42 SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 23,393.00	
TOTAL LABOUR CHARGES	:	\$ 10,052.00	
GRAND TOTAL	:	\$ 33,445.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian L
09/11/20
Hes.