

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Oct 2020 16:46	Clm Veh Model Changed		[] Merimen Administrator
2	16 Oct 2020 16:46	Clm Created	Reg No: SLX7340D. Policy No: 1800033993-01. Acct Date: 2020/10/15. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA120090745	[I] Merimen Administrator
3	20 Oct 2020 13:18	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	20 Oct 2020 13:18	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	20 Oct 2020 13:18	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	20 Oct 2020 13:18	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/10/29	[A] LEE SU THING
7	20 Oct 2020 13:18	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	20 Oct 2020 13:18	Clm Registration Modified	Rep:1137->200611.	[A] LEE SU THING
9	20 Oct 2020 13:18	Clm Veh Model Changed	(205236) AUDI Q2 999cc 1.0 TFSI S TRONIC (A).	[A] LEE SU THING
10	20 Oct 2020 13:18	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
11	20 Oct 2020 14:48	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	20 Oct 2020 14:48	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	20 Oct 2020 14:48	Clm Dtl Modified	JPJ Reg. Date: -> 2018/04/09.	[A] Elaine Kuan Hwa Meen
14	20 Oct 2020 14:48	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	20 Oct 2020 15:25	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/10/29	[A] DENISE TAY KWEE CHENG
16	20 Oct 2020 15:25	Adj Mandate Request	Cur.Reg:13357.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
17	20 Oct 2020 17:58	Clm Registration Modified	Acct Time:17:45:00->17:00:00. Pol No:1800033993-01->1800033993.	[I] Subramaniam, Divyashni
18	26 Oct 2020 18:34	Clm Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 1000.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Abu Kassim, Noor Mariesa
19	26 Oct 2020 18:34	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
20	27 Oct 2020 15:42	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/10/29. Mandate Remarks: Authorise repair. Re-inspection to be done for damage check and supplementary items / labour with clear photos. Why the FRONT BUMPER SPOILER need to be replace it's only dislodge? damage photos?	[I] Koh, Victor-CK
21	27 Oct 2020 15:42	Adj Mandate Set	Approved:9863.00:Authorise repair. Re-inspection to be done for damage check and supplementary items / labour with clear photos. Why the FRONT BUMPER SPOILER need to be replace it's only dislodge? damage photos?Reinsp:Yes.	[I] Koh, Victor-CK

Date From   
 Date To   
 Audit Type 

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2615197	20 Oct 2020 14:48:54	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLX7340D		11.00