

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 56323**  
Date Estimated : **19/10/2020**  
Prepared By : **Joseph Yaguel**

### - ESTIMATE REPAIR FOR -

**Wong Bee Hua Susan**  
**5 Siglap Road**  
**#07-33**

**Singapore 448908**

### - ACCOUNT - 121

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SBV8813D</b>	<b>WBALX32050C952009</b>	<b>30/05/2012</b>	<b>650i/2(A)</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	NETT
To replace front bumper and attachments including make good the front left fender and knock out dented area caused by the accident.	1,700.00	1,700.00
To respray front bumper and front left fender.	1,730.00	1,730.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	450.00	450.00
To replace front left wheel rim including balancing. (1x).	80.00	80.00
To check electrical wiring system at the front section for proper function.	150.00	150.00
Sundries	80.00	80.00

DESCRIPTION	UNIT PRICE	QTY	NETT
ALLOY RIM 81/2JX19 V SPOKE 331	1,231.40	1.00	1,231.40
FRT BUMPER TRIM PRIMED (PDC)	1,565.90	1.00	1,565.90
BMW EMBLEM	71.60	1.00	71.60

### # SUPPLEMENTARY ITEMS

Total Labour :	4,190.00
Total Parts :	2,868.90
Total Labour & Parts :	7,058.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,058.90
GST @7%:	494.12
Grand Total :	7,553.02