

AUTOPROBE CONSULTANTS

To: AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Our Ref.: SVY191000103
Date: 14/04/2020

AUTOMOBILE INSPECTION REPORT

1. SURVEY TYPE: THIRD PARTY

Assignment Date:	16/10/2019	Your Reference:	S9M023TL
Vehicle Inspected:	GBA-4277-M	Policy Excess:	-
Insured Vehicle:	PC -8868-E		
Date of Accident:	15/10/2019	Surveyed / Assessed Date:	16/10/2019
Repairer / Survey at:	CHOO MOTOR SPRAY PAINTER	Resurvey Date:	18/10/2019, 21/10/2019

2. VEHICLE PARTICULARS:

Make & Model:	OPEL COMBO-C 1.3DTJ MTA E4	General Condition:	FAIR
Registration Date:	02/07/2007	Colour:	SILVER
Engine Capacity:	1248	Odometer (km):	230902
Chassis No.:	W0L0XCF2574306606	Steering:	IN ORDER
Engine No.:	Z13DTJ1948932	Brake:	IN ORDER

3. TYRE CONDITION:

	Size	Make	Thread Depth (%)
FRONT LEFT	185/60R15	BRIDGESTONE	60
FRONT RIGHT	185/60R15	BRIDGESTONE	60
REAR LEFT	185/60R15	BRIDGESTONE	60
REAR RIGHT	185/60R15	BRIDGESTONE	60

4. DESCRIPTION OF DAMAGES:

The vehicle sustained damages mainly at the rear right portion.

AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

5. ADJUSTMENT SUMMARY:

Original Estimate: -
Revised: -
Final Adjustment: -
Estimated Repair Duration: 4.00 Working Days

6. ESTIMATED VALUE (at time of accident):

Market Value: \$15,000.00 (COE Expiry: 01/07/2022)
LTA Rebate: \$9,236.00 (as at 15/10/2019)
Nett: \$5,764.00

7. SPECIAL REMARKS

Despite our request, the repairer did not provide us with the repair estimate.

Estimated Repair Cost: \$4,300/-

8. INSPECTIONS

Pre-repair: 16/10/2019
Dismantled Parts: 18/10/2019
Post-repair: 21/10/2019

The Inspection was conducted on a "Without Prejudice" basis.

Assessor: TAY BH

AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019



Photograph 2 of 52



Photograph 1 of 52



Photograph 4 of 52



Photograph 3 of 52

AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 6 of 52



Photograph 5 of 52



Photograph 8 of 52



Photograph 7 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 10 of 52



Photograph 9 of 52



Photograph 12 of 52



Photograph 11 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 14 of 52



Photograph 13 of 52



Photograph 16 of 52



Photograph 15 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 18 of 52



Photograph 17 of 52



Photograph 20 of 52



Photograph 19 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 22 of 52



Photograph 21 of 52



Photograph 24 of 52



Photograph 23 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 26 of 52



Photograph 25 of 52



Photograph 28 of 52



Photograph 27 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 30 of 52



Photograph 29 of 52



Photograph 32 of 52



Photograph 31 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 34 of 52



Photograph 33 of 52



Photograph 36 of 52



Photograph 35 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 38 of 52



Photograph 37 of 52



Photograph 40 of 52



Photograph 39 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 42 of 52



Photograph 41 of 52



Photograph 44 of 52



Photograph 43 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 46 of 52



Photograph 45 of 52



Photograph 48 of 52



Photograph 47 of 52



AUTOPROBE CONSULTANTS

Your Ref.: S9M023TL
Our Ref.: SVY191000103

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

Photograph 50 of 52



Photograph 49 of 52



Photograph 52 of 52



Photograph 51 of 52

