

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6108 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	20/LP/OD-405 (10)
Policy No:	Z19VP05025086	Date of Loss:	17/10/2020
Vehicle Reg. No.:	SLU2070G	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Thrd Party Involved?	YES
Insured/Claimant:	KOH POH LYE		
Driver:	KOH MING JUN		

Make/Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Vehicle Reg. Date:	27/11/2017
Vehicle Colour:	BROWN	Chassis No:	JF1SJ5KC5JG100098
Engine No:	FB20YB39278		
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO
5

not Affected

2/P 5

24,155 4500

the 2nd sedan party

Description of Accident/Loss: REFER TO POLICE REPORT: T/20201017/2097.

Remarks: VEHICLE NOT IN.

Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	2,748.50
Miscellaneous Items	0.00
Labour	2,095.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	4,843.50
+ GST 7.00% (S\$)	339.05
Nett Amount (S\$)	5,182.55

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Repairer Estimates

Page 2 of 3

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Oct 2020)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SLU2070G/20/10/2020 10:53

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR RH DOOR <i>Body</i>	0.00	0.00	*495.00 F
2	1		*REAR RH DOOR STICKER <i>new</i>	0.00	0.00	*55.00 F
3	1		*REAR RH DOOR LOWER PROTECTOR <i>new</i>	0.00	0.00	*120.00 F
4	8		*PROTECTOR CLIP <i>new</i>	0.00	0.00	*18.00 F
5	1		*FRT RH DOOR <i>Body</i>	0.00	0.00	*495.00 F
6	1		*FRT RH DOOR LOWER PROTECTOR <i>new</i>	0.00	0.00	*180.00 F
7	8		*PROTECTOR CLIP <i>new</i>	0.00	0.00	*16.00 F
8	1		*FRT FENDER RH <i>Body</i>	0.00	0.00	*180.00 F
9	1		*FRT FENDER INNER COWLING <i>Dis</i>	0.00	0.00	*95.00 F
10	10		*INNER COWLING CLIP <i>new</i>	0.00	0.00	*20.00 F
11	1		*FRT FENDER LOWER PROTECTOR RH <i>new</i>	0.00	0.00	*25.00 F
12	4		*PROTECTOR CLIP <i>new</i>	0.00	0.00	*8.00 F
13	1		*REAR RH SPORT RIM (ORI 17 INCH)	0.00	0.00	*650.00 F ?
14	1		*REAR FENDER WHEEL ARC RUBBER SEAL RH <i>new</i>	0.00	0.00	*55.00 F

F=Franchise part.

Sub Total (S\$)

2,390.00

+ Margin on L,N Items 15.00% (S\$)

358.50

Total Parts (S\$)

2,748.50

SME Motor Pte Ltd/SLU2070G/20/10/2020 10:53. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Repairer Estimates

Page 3 of 3

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00 20
2	TRANSFER DOOR COMPONENTS FROM OLD TO NEW	New	150.00 120
3	REPLACE REAR RIM & BALANCING	New	50.00 X
4	WHEEL ALIGNMENT	New	65.00 60
5	LABOUR CHARGE	New	850.00 400
6	SPRAY PAINTING	New	950.00 750
Gross Labour Cost (\$\$)			2,095.00

SME Motor Pte Ltd/SLU2070G/20/10/2020 10:53. Not valid without Reference section.
Generated using Merlimen e-Claims IEAS

< END OF ESTIMATES >