

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

CC4/FCI20011372/Aea3

CHIN XUN KAI

BLK 455A ANG MO KIO ST 44 #18-03

SINGAPORE 561455

ESTIMATE

Repair Code : CLM15056

Date in : 19/10/2020

Vehicle Num. : SJF3682L

Model : TOYOTA VIOS G AUTO

Chassis/Eng# : MR053HY9305064262/1NZX753838

Contact : 92320286

TP 1st Cap.
Ashes.

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Rehanded</i>	1	495.70	✓ 495.70
FRONT BUMPER 'LOGO' EMBLEM <i>new</i>	1	66.20	✓ 66.20
FRONT BUMPER CENTER GRILLE <i>new</i>	1	462.40	+ 462.40
FRONT BUMPER CENTER GRILLE OUTER CHROME MOULDING <i>new</i>	1	107.10	✓ 107.10
FRONT BUMPER INNER TOP GARNISH <i>could</i>	1	109.80	✓ 109.80
FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	399.50	✓ 399.50
FRONT BUMPER RH FOGLAMP <i>could</i>	1	310.40	✓ 310.40
FRONT BUMPER RH FOGLAMP GARNISH <i>could</i>	1	84.70	✓ 84.70
FRONT BUMPER SIDE RETAINER L/R <i>RH could</i>	2	64.60	64.60 129.20
FRONT CROSS MEMBER <i>Bent</i>	1	1892.90	1552 1,892.90
FRONT RH DRIVE SHAFT <i>Bent</i>	1	1384.10	✓ 1,384.10
FRONT RH FENDER <i>Dented</i>	1	637.70	✓ 637.70
FRONT RH FENDER INNER BRACKET <i>Bent</i>	1	58.00	✓ 58.00
FRONT RH FENDER INNER GARNISH (VERTICAL) <i>could</i>	1	54.10	✓ 54.10
FRONT RH FENDER INNER SHIELD COVER <i>torn</i>	1	175.60	✓ 175.60
FRONT RH HEADLAMP <i>cut</i>	1	558.90	✓ 558.90
FRONT RH KNUCKLE ARM <i>Damaged</i>	1	558.90	942 558.90
FRONT RH KNUCKLE ARM BEARING <i>New</i>	1	183.80	✓ 183.80

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

CHIN XUN KAI

BLK 455A ANG MO KIO ST 44 #18-03

SINGAPORE 561455

Contact : 92320286

ESTIMATE

Repair Code : CLM15056

Date in : 19/10/2020

Vehicle Num. : SJF3682L

Model : TOYOTA VIOS G AUTO

Chassis/Eng# : MR053HY9305064262/1NZX753838

FRONT RH LOWER ARM <i>Bent</i>	1	1195.40	<i>495</i> ✓	1,195.40
FRONT RH SHOCK ABSORBER <i>Bent</i>	1	463.80	✓	463.80
FRONT RH SHOCK ABSORBER TOP MOUNTING <i>new</i>	1	223.30	✗	223.30
FRONT RH SIDE MIRROR ASSY <i>Repair</i>	1	1189.60	✗	1,189.60
FRONT RH SIDE MIRROR COVER <i>Repair</i>	1	108.60	✗	108.60
FRONT RH SPORT RIM <i>new</i>	1	1748.10	<i>455(SW)</i>	1,748.10
FRONT RH STABILIZER LINK <i>Bent</i>	1	213.60	✓	213.60
FRONT RH TIE ROD END <i>Bent</i>	1	117.70	✓	117.70
FRONT STEERING RACK AND PINION <i>Damage</i>	1	1955.40	<i>1373</i>	1,955.40
FRONT WASHER TANK <i>Replaced</i>	1	145.80	✓	145.80
FRONT WASHER TANK MOTOR <i>new</i>	1	293.00	✗	293.00
Subtotal before discount				15,323.30
Percentage discount 25%				3,830.83
Sub-total 1				11,492.48
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	<i>30</i> ✓	50.00
FRONT RH 185/65R15 TYRE <i>new all</i>	1	350.00	✗	350.00
FRONT RH FENDER INNER SHIELD COVER CLIPS - SET <i>new</i>	1	30.00	✓	30.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHIN XUN KAI
BLK 455A ANG MO KIO ST 44 #18-03
SINGAPORE 561455

Contact : 92320286

ESTIMATE

Repair Code : CLM15056

Date in : 19/10/2020

Vehicle Num. : SJF3682L

Model : TOYOTA VIOS G AUTO

Chassis/Eng# : MR053HY9305064262/1NZX753838

Subtotal before discount	430.00
Percentage discount 0%	0.00
Sub-total 2	430.00
Parts-total	11,922.48

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

30 80.00

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

300 400.00

To road test driving, check and resetting wheel alignments system.

✓ 80.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

500 1,000.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

500 1,000.00

To apply anti-rust chemical on repaired and replaced panel.

50 120.00

Labour Total

2,680.00

Parts & Labour Total

14,602.48

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
h/s 20/10/20

067ays.

total: 8639.82

L/S: 6.9K ✓