

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SGR1963L [YOUR INSURED] & SKP8110Z [OUR CLIENT]
ON 18/10/2020.

ESTIMATED REPAIR COSTS FOR SKP8110Z

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	REAR BUMPER <i>new</i>	\$ 683.20	X
1PC	REAR BUMPER SIDE GARNISH RH <i>new</i>	\$ 174.90	X
1PC	REAR BUMPER SIDE RETAINER RH <i>new</i>	\$ 48.20	X
1PC	REAR END PANEL <i>new</i>	\$ 692.30	X
1PC	REAR FENDER RH <i>new</i>	\$ 1,012.00	X

PARTS SUM: \$ 2,610.60

PARTS LESS 20%: \$ 522.12

PARTS TOTAL: \$ 2,088.48

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR BUMPER CLIPS <i>new</i>	\$ 50.00	X
*	TO SUPPLY REVERSE SENSOR <i>new</i>	\$ 300.00	X
*	TO SUPPLY REAR END PANEL SEALANT <i>new</i>	\$ 80.00	X
*	TO SUPPLY REAR FENDER SEALANT <i>new</i>	\$ 80.00	X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 800.00	<i>new</i>
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 800.00 2001	
*	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$ 150.00	<i>new</i>
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	<i>new</i>
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	<i>new</i>

20/11/2020 c 0915h
Hua Andri

LABOUR & S/N TOTAL: \$ 2,760.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 4,848.48

71Pst.
Phon after rep. *2 days.*
you
LKK Auto

LIS \$200.00