

ASSIGNMENT

COE Aug 2028

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLM 4526MPolicy No. 29145681 MKFClaims No. 629988


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal: or Market Value: _____

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 22 ~~15~~ days Res.: Yes or NoLum Sum: 10 ~~20~~ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHIA 7789L Yr Regn: Aug/2020Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius c.c. 1798Colour: Blue A/C: Insured / Std / NI / NASp.Reading: N.A. T/Radio: Insured / Std / NI / NAEng/No: 2ZR2G80218C/No: STDKB3FU003091459Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim orTyre Size: F: 195/65 R15R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Devanti

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 18/10/2020 D.O.A. 20/10/2020Survey held at Bifrost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front 7 N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSG. SLM 4526M
	06/05/21 - Invoice 2/5 42,000/- with
	New model Toyota Prius. 22 days of work
	(Red 21,799.46, 34%)
	4/Srm of 103 applied as most parts damaged plus so not many
	second hand hard parts in market to replace damaged parts.
	BV calculation r/n to separate paper.

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 6/5/21-Typist

Days Of Repair: 22Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S+RS SI

Photos

Others

TOTAL

Report Format: MerimenLump Sum / I.B.I: (\$ LS \$42,000)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

SHA 7789L Book Value

Purchase Cost less PARF =

$$79745.93 - 8718.00 = 71027.93$$

96 months

$$= 739.87 / \text{mth.}$$

Value balanced = ~~9~~ 94 months

$$= 69,547.78 + \text{PARF}$$

$$= 78,265.78 \text{ Book Value at loss.}$$

Less LTA amt

$$31,498.00 = \underline{\underline{46,767.78}}$$

Net Value

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/10/2020 16:02
Date Of Accident	18/10/2020 10:15
Exact Location Of Accident	EUNOS ROAD 5 X EUNOS AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7789L
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGETAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	LING SWEE THIAN
NRIC No	SXXXX855B
Date Of Birth	04/07/1973
Occupation	OUTDOOR
Date Of Driving Pass	01/07/1996
Driving Experience	24 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98508799
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 468A FERNVALE LINK #17-539
Postcode	791468
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20201018/2063 * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW4526M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	THAN KAR WEE
NRIC/Passport Number	
Contact Number	97942384
Address	

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LING SWEE THIAN

Approximate Age

Injuries Sustain

RIGHT SHOULDER AND LEFT LEG

Injured person in which vehicle?

SHA7789L

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

UNKNOWN (PAX)

Approximate Age

Injuries Sustain

UNSURE

Injured person in which vehicle?

SHA7789L

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

A - SHA 7789L
B - SLW 4526M

Along Eunosa Road 5 x Eunosa Ave 3

Along Eunus Road 5 x Eunus Ave 3

Refer to Police Report : T/20201018/2063

Refer to Police Report : T/20201018/2063

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: Regina
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20201018/2063

1 of 4

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

Report No. T/20201018/2063

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/10/2020 16:36		Vide Report No.: G/20201018/0137		Station Diary No.: 50	
Informant's Particulars					
Name of Informant: LING SWEE THIAN			Address: APT BLK 468A FERNVALE LINK #17-539 SINGAPORE 791468		
ID Type / ID No.: NRIC NO / S7323855B			Contact No.: Home/Office: Mobile: 98508799		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 04/07/1973	Type of Informant: Driver		
Race: Chinese			Language: Chinese		Institution / School Name:
Occupation: Sales and related associate professional nec			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/10/2020 10:15	Type of Location: X-Junction
Location: EUNOS AVENUE 3				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA7789L	Car				Seriously Damaged	1
SLM4526M	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20201018/2063

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

2 of 4

Report No. T/20201018/2063

CONTINUATION OF REPORT

Passenger			
Name	Unknown Passenger		ID No. NIL
Related Vehicle	SHA7789L (Car)		Contact No. 87517831
Hospital/Clinic	KHOO TECK PUAT HOSPITAL Tan Tock Seng Hospital		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	18/10/2020	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LING SWEE THIAN		ID No. S7323855B
Related Vehicle	SHA7789L (Car)		Contact No. 98508799
Hospital/Clinic	KHOO TECK PUAT HOSPITAL Tan Tock Seng Hospital		Class of Driving Licence & Expiry Date Class: 2B,3 Date of Expiry: NIL
Date Treatment	18/10/2020	Date Discharge	18/10/2020
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Than Kar Wee		ID No. S7145117H
Related Vehicle	SLM4526M (Car)		Contact No. 97942384
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/10/2020 at about 1015hrs, I was driving my Taxi (registration plate number: SHA7789L) fetching a passenger (C/N: 97942384) around Eunos Road 5 towards Sims Avenue. While along the junction of Eunos Road 5 and Eunos Avenue 3, a car bearing a registration plate number SLM4526M driving along Eunos Avenue 3 towards Singpost, collided to my Taxi's side bonnet, our vehicle then went side way and his vehicle's driver side door collided to my taxi's passenger door. The car the went and went towards the walkway beside the temple. Me and my passenger left pain after the accident. Subsequently, we contacted the police and ambulance. Both me and my passenger was conveyed by ambulance to Tan Tock Seng Hospital. I sustained slight injuries at my right shoulder area and left leg. I was given three days of medical leave. My Taxi was badly damaged and was towed back to the workshop. I do not know the cost to repair the taxi.



**SINGAPORE
POLICE FORCE**



T/20201018/2063

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

3 of 4

Report No. T/20201018/2063

CONTINUATION OF REPORT

I would like to state that, there is a stop line along Eunos Avenue 3 before the junction, as such the car should stop before the stop line, however the car did not stop at the stop line.

The other driver details as follows: Than Kar Wee, S7145117H, Male/Chinese, DOB: 09/12/1971, B 28 Tanglin Halt Rd #06-100, C/N: 97942384.



**SINGAPORE
POLICE FORCE**



T/20201018/2063

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

4 of 4

Report No. T/20201018/2063

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
L /
Sgt 3 CHIN JING SI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
SI YEO CHUN JIAN
Contact No.: 65476213

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
18/10/2020 16:36

Classification Of Case:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

OMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the Policyholder)
Date & Time: 19.10.2020
@ 14:45 hrs

Reporting Centre Personnel's Signature
Name: *Adnan*
NRIC/FIN No.:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 20-Oct-20

MODEL: TOYOTA PRIUS

INSURANCE: MSIG

VEHICLE NO.: SHA 7789 L

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR FENDER, LH <i>repaired</i>	1	\$ 1,181.00	\$ 1,181.00	X
REAR DOOR RUBBER SEAL OUTER <i>SVC</i>	1	\$ 364.03	\$ 364.03	X
PANEL SUB-ASSY, REAR DOOR, LH <i>Enc 1258.30</i>	1	\$ 1,776.09	\$ 1,776.09	✓
REAR DOOR HINGE UPPER <i>SVC</i>	1	\$ 116.17	\$ 116.17	X
REAR DOOR HINGE LOWER <i>SVC</i>	1	\$ 116.17	\$ 116.17	X
REAR DOOR CHECK <i>SVC</i>	1	\$ 215.96	\$ 215.96	X
REAR DOOR TRIMBOARD <i>Dem Rear 549.30</i>	1	\$ 1,023.34	\$ 1,023.34	? ✓
MOTOR, POWER WINDOW REGULATOR FRT, LH <i>St 1329.35</i>	1	\$ 1,329.35	\$ 1,329.35	? ✓
REAR DOOR OUTER HANDLE <i>Ext 228.40</i>	1	\$ 131.27	\$ 131.27	✓
REAR DOOR OUTER MOULDING <i>St</i>	1	\$ 181.52	\$ 181.52	✓
REAR DOOR RUBBER SEAL OUTER <i>repaired</i>	1	\$ 364.03	\$ 364.03	X
LOCK ASSY, BACK DOOR <i>Dem 554.60</i>	1	\$ 626.85	\$ 626.85	? ✓
Door Centre Pillar Outer (LH/RH) <i>repaired 1590.60</i>	1	\$ 2,245.13	\$ 2,245.13	X ✓
Door Centre Pillar enforcement (LH/RH) <i>Htl</i>	1	\$ 1,218.55	\$ 1,218.55	X
PANEL SUB-ASSY, FRONT DOOR, RH <i>St 1264.00</i>	1	\$ 1,784.14	\$ 1,784.14	✓
FRONT DOOR OUTER HANDLE (LH) <i>repaired</i>	1	\$ 534.82	\$ 534.82	X
FRONT DOOR HINGE UPPER <i>Htl</i>	1	\$ 116.17	\$ 116.17	X
FRONT DOOR HINGE LOWER <i>Htl</i>	1	\$ 128.73	\$ 128.73	X
FRONT DOOR CHECK <i>Htl</i>	1	\$ 216.69	\$ 216.69	X
FRONT DOOR KEY LOCK SET <i>Htl</i>	1	\$ 605.39	\$ 605.39	X
FRONT DOOR COMFORT LOGO <i>Htl SH</i>	1	\$ 105.86	\$ 105.86	✓ SH
BONNET <i>Enc 983.10</i>	1	\$ 1,341.63	\$ 1,341.63	✓
INSULATOR, HOOD <i>St 393.30</i>	1	\$ 561.92	\$ 561.92	✓
INSULATOR CLIPS <i>Htl</i>	1	\$ 5.08	\$ 5.08	✓
BONNET RUBBER <i>SVC</i>	1	\$ 50.11	\$ 50.11	X
BONNET CABLE <i>Htl</i>	1	\$ 117.44	\$ 117.44	X
BONNET HINGE (RH) <i>St</i>	1	\$ 123.79	\$ 123.79	✓
BONNET HINGE (LH) <i>St</i>	1	\$ 123.79	\$ 123.79	✓
BONNET LOCK <i>St</i>	1	\$ 187.16	\$ 187.16	✓
CATCH, HOOD AUXILIARY HOOK <i>repaired</i>	1	\$ 12.14	\$ 12.14	X
RADIATOR GRILLE <i>broken 434.80</i>	1	\$ 618.24	\$ 618.24	✓
RADIATOR GRILLE EMBLEM <i>broken</i>	1	\$ 124.21	\$ 124.21	✓
FRONT BUMPER COVER <i>turn</i>	1	\$ 705.61	\$ 705.61	✓
FRONT BUMPER REINFORCEMENT <i>Dem 716.60</i>	1	\$ 982.97	\$ 982.97	✓
FRONT BUMPER REINFORCEMENT ABSORBER <i>Dem 163.31</i>	#2	\$ 163.31	\$ 163.31	✓
FRONT BUMPER LOWER REINFORCEMENT <i>Dem 364.20</i>	1	\$ 514.07	\$ 514.07	✓
FRONT BUMPER LOWER REINFORCEMENT BRACKET <i>St</i>	#2	\$ 465.80	\$ 465.80	✓
FRONT BUMPER SPONGE <i>turn</i>	1	\$ 111.23	\$ 111.23	✓
FRONT BUMPER LOWER GRILLE <i>broken / dislodged</i>	1	\$ 209.75	\$ 209.75	✓
LAMP ASSY, FOG, RH <i>Ext 951.40</i>	1	\$ 1,298.58	\$ 1,298.58	✓
LAMP ASSY, FOG, LH <i>Ext 951.40</i>	1	\$ 1,298.58	\$ 1,298.58	✓
FRONT BUMPER CLIPS <i>Htl</i>	1	\$ 31.05	\$ 31.05	✓

12,803.57

FRONT BUMPER SIDE RETAINER <i>N/S distorted</i>	77.10	1	\$ 108.69	\$ 108.69	✓
FRONT LOWER CROSSMEMBER <i>new st</i>	320.60	1	\$ 504.89	\$ 504.89	✓
FRONT UNDER COVER <i>st broken</i>		1	\$ 255.20	\$ 255.20	✓
ENGINE UNDER COVER (RR) <i>st deformed</i>	457.40	1	\$ 645.62	\$ 645.62	✓
FRONT BUMPER TOP GARNISH <i>broken</i>	225.40	1	\$ 318.15	\$ 318.15	✓
COVER, FRONT BUMPER HOLE, RH <i>distorted</i>		1	\$ 40.06	\$ 40.06	✓
COVER, FRONT BUMPER HOLE, LH <i>distorted</i>		1	\$ 40.06	\$ 40.06	✓
ABSORBER, FRONT BUMPER, LOWER <i>broken</i>		1	\$ 180.25	\$ 180.25	✓
UNIT ASSY, HEADLAMP, RH (LED) <i>broken</i>	2637.60	1	\$ 4,876.73	\$ 4,876.73	✓
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>	2637.60	1	\$ 4,876.73	\$ 4,876.73	✓
HEADLAMP ECU <i>N/S broken</i>	437.76	1	\$ 963.49	\$ 963.49	✓
HEAD LAMP PANEL (RH) <i>st</i>	240.10	1	\$ 338.90	\$ 338.90	✓
HEAD LAMP PANEL (LH) <i>st</i>	240.10	1	\$ 338.90	\$ 338.90	✓
TOP PANEL CENTRE <i>st</i>	364.98	1	\$ 515.17	\$ 515.17	✓
TOP PANEL SIDE <i>N/S st</i>	149.50	1	\$ 205.94	\$ 205.94	✓
BRACE PANEL <i>st</i>		1	\$ 106.14	\$ 106.14	✓
RADIATOR ASSY <i>2 st</i>	1841.80	1	\$ 2,599.70	\$ 2,599.70	✓
COOLANT <i>NW</i>		1	\$ 63.52	\$ 63.52	X
DEFLECTOR, RADIATOR SIDE, RH <i>deformed</i>		1	\$ 117.86	\$ 117.86	✓
DEFLECTOR, RADIATOR SIDE, LH <i>deformed</i>		1	\$ 117.86	\$ 117.86	✓
*RADIATOR TOP HOSE <i>2 deformed</i>		1	\$ 60.74	\$ 60.74	✓
*RADIATOR TOP HOSE <i>NW</i>		1	\$ 60.13	\$ 60.13	X
RADIATOR SPARE TANK HYBRID <i>2 mainly broken</i>		1	\$ 177.57	\$ 177.57	✓
RADIATOR BOTTOM MOUNTING <i>NW</i>		1	\$ 38.82	\$ 38.82	X
STAY, RADIATOR SUPPORT, RH <i>NW</i>		1	\$ 92.74	\$ 92.74	X
STAY, RADIATOR SUPPORT, LH <i>NW</i>		1	\$ 92.74	\$ 92.74	X
RADIATOR FAN BLADE (RH) <i>2 svc</i>		1	\$ 329.02	\$ 329.02	✓
RADIATOR FAN BLADE (LH) <i>2 broken</i>		1	\$ 329.02	\$ 329.02	✓
RADIATOR FAN MOTOR (RH) <i>2 NW</i>		1	\$ 767.43	\$ 767.43	✓
RADIATOR FAN MOTOR (LH) <i>2 Deformed NW</i>		1	\$ 767.43	\$ 767.43	✓
RADIATOR FAN COWLING (LH/RH) <i>2 broken</i>		2	\$ 637.01	\$ 1,274.02	✓
RESERVE TANK ASSY, RADIATOR W/O CAP <i>NW</i>		1	\$ 557.97	\$ 557.97	X
HORN (1 PC) <i>svc</i>		1	\$ 159.09	\$ 159.09	X
AIR CLEANER TOP COVER <i>2 broken</i>	446.50	1	\$ 630.23	\$ 630.23	✓
AIR CLEANER BOTTOM COVER <i>2 broken</i>	947.80	1	\$ 1,337.82	\$ 1,337.82	✓
CONDENSER ASSY, W/RECEIVER <i>2 st</i>	1336.30	1	\$ 1,886.61	\$ 1,886.61	✓
FENDER SUB-ASSY, FRONT RH <i>3vc</i>	977.80	1	\$ 1,334.29	\$ 1,334.29	✓
FENDER SUB-ASSY, FRONT LH <i>3vc</i>	977.80	1	\$ 1,334.29	\$ 1,334.29	✓
FRONT HOUSING ASSY <i>2 N/S Deformed</i>		1	\$ 1,334.23	\$ 1,334.23	✓
FRONT FENDER SHIELD <i>N/S deformed / torn o/s NW</i>		2	\$ 280.18	\$ 560.37	✓
FRONT FENDER SHIELD CLIP <i>Nec N/S o/s NW</i>		2	\$ 21.03	\$ 42.06	✓
FRONT FENDER HYBRID EMBLEM, LH <i>Nec</i>	54.60	1	\$ 122.09	\$ 122.09	✓
FRONT FENDER HYBRID EMBLEM, RH <i>Nec</i>	54.60	1	\$ 122.09	\$ 122.09	✓
BRACKET, FRONT SIDE PANEL, RH <i>NW</i>		1	\$ 121.81	\$ 121.81	X
BRACKET, FRONT SIDE PANEL, LH <i>NW</i>		1	\$ 121.81	\$ 121.81	X
FRONT WINDSCREEN GLASS <i>Crack</i>	1627.30	1	\$ 2,296.93	\$ 2,296.93	✓
FRONT WINDSCREEN GLASS MOULDING <i>Nec</i>		1	\$ 259.15	\$ 259.15	✓
FRONT WINDSCREEN GLASS MOULDING LOWER <i>Nec</i>		1	\$ 294.44	\$ 294.44	✓
FRONT WINDSCREEN SIDE GARNISH <i>svc</i>		2	\$ 263.10	\$ 526.21	X
WIPER TOP GARNISH <i>deformed</i>	668.32	1	\$ 943.33	\$ 943.33	✓
STEERING WHEEL AIRBAG <i>Activated</i>	2377.30	1	\$ 3,240.20	\$ 3,240.20	✓
AIR BAG ASSY, DRIVER SIDE LOWER <i>Activated</i>		1	\$ 2,249.37	\$ 2,249.37	✓
DASHBOARD AIR BAG ASSY PASSENGER <i>Activated</i>	3240.30	1	\$ 4,573.54	\$ 4,573.54	✓
SENSOR, AIR BAG, FRONT RH <i>Activated</i>		1	\$ 438.27	\$ 438.27	✓

29,277.00

SUB TOTAL	42080.57			\$ 69,117.42
LESS 20% 25%				\$ 13,823.48
DISCOUNTED TOTAL	31560.42			\$ 55,293.93
REAR DOOR COMFORT & APPS STICKER <i>new</i>	SN	1	\$ 113.00	\$ 113.00 ✓
FRONT NO. PLATE TRM COVER <i>st</i>	SN	1	\$ 43.00	\$ 25/- 43.00 ✓
FRONT NO. PLATE GARNISH <i>delivered</i>	List SN	1	\$ 140.00	\$ 140.00 ✓
FRONT BUMPER LOGO <i>MS</i>	SN	1	\$ 123.00	\$ 123.00 X
FRONT NO. PLATE <i>delivered</i>	SN	1	\$ 36.00	\$ 36.00 15/-
SUB TOTAL	258.86			\$ 455.00
Labour Charge				
Panel Beating		1	\$1,800.00	\$ 1,800.00 1400/-
Spray Painting Charge		1	\$1,600.00	\$ 1,600.00 1200/-
Wiring Charge		1	\$200.00	\$ 200.00 30/-
Tuff Kote		1	\$180.00	\$ 180.00 40/-
Towing Charge		1	\$80.00	\$ 80.00 44
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$ 150.00 80/-
Remove/Refix Undercarriage (RR)		1	\$400.00	\$ 400.00 44
Re-set Rear ABS System		1	\$400.00	\$ 400.00 44
Transfer of Door Mechanism FRONT		1	\$80.00	\$ 80.00 60/-
Transfer of Door Mechanism REAR		1	\$80.00	\$ 80.00 60/-
Re-set Rear Power Window System		1	\$200.00	\$ 200.00 44
Four Wheel Alignment	3790.00	1	\$120.00	\$ 120.00 44
Remove/Refix Radiator		1	\$90.00	\$ 90.00 50/-
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$ 130.00 80/-
Remove/Refix Fuse Box		1	\$120.00	\$ 120.00 80/-
Remove/Refix Front Windscreen Glass		1	\$120.00	\$ 120.00 80/-
Front Chassis Alignment Charge		1	\$220.00	\$ 220.00 150/-
Remove/Refix Air Bag/Steering Wheel/Dashboard/Seat		1	\$550.00	\$ 550.00 180/-
Re-programme Air Bag & Safety Belt System		1	\$550.00	\$ 550.00
Reset Safety Belt		1	\$120.00	\$ 120.00
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$ 550.00 } 300/-
TOTAL LABOUR				\$ 7,740.00
ESTIMATE TOTAL			63,799.46	\$ 63,488.93
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

20/10/2020 e 1700hrs

Not Antimal

35609.28

Supp 11420-64

1 year

Part by Part.

47029.92

LKK Auto

22 days

4542,000/-

Provide BV before finalisation

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 26-Oct-20

MODEL: TOYOTA PRIUS

INSURANCE: MSIG

VEHICLE NO.: SHA 7789 L (S)

11,420.64

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
FRONT FENDER TOP COVER (LH/RH) dislodged	2	\$ 425.00	\$ 850.01	✓
Rocker Panel Outer Garnish Dented 576.00	1	\$ 813.02	\$ 813.02	✓
FRONT BUMPER SIDE GRILLE (RH) dislodged / broken LH	1	\$ 209.75	\$ 209.75	✓
FRONT BUMPER SIDE RETAINER (RH) sn	1	\$ 108.69	\$ 108.69	X
TOP PANEL SIDE (RH) st 149.50	1	\$ 205.94	\$ 205.94	✓
AIR DUCT Dam	1	\$ 182.65	\$ 182.65	✓
AIR DUCT HOSE damaged	1	\$ 238.83	\$ 238.83	✓
TRAY, BATTERY broken	1	\$ 60.41	\$ 60.41	✓
WIPER TOP GARNISH PANEL Dented / st	1	\$ 972.50	\$ 972.50	✓
SIDE RAIL PANEL SUPPORT (LH/RH) st 230.75 x 2 = 461.50	2	\$ 428.60	\$ 857.20	✓
HEADLAMP PANEL INNER (LH/RH) gy	2	\$ 338.40	\$ 676.80	X
FRONT CHASSIS MEMBER (LH) st	1	\$ 2,838.24	\$ 2,838.24	✓
FRONT BUMPER EMBLEM LOGO GARNISH distorted	1	\$ 168.80	\$ 168.80	✓
FRONT SAFETY BELT (LH/RH) actuated 995.10 x 2 = 1990.20	2	\$ 1,465.14	\$ 2,930.27	✓
SENSOR, AIR BAG, FRONT reported	1	\$ 801.45	\$ 801.45	X
GEARBOX MOUNTING Dam 299.30	1	\$ 758.80	\$ 758.80	✓
ENGINE MOUNTING sn	1	\$ 540.18	\$ 540.18	X
ENGINE UNDER MOUNTING st	1	\$ 244.06	\$ 244.06	✓
ENGINE CROSS MEMBER st / Dented 2179.40	1	\$ 3,534.96	\$ 3,534.96	✓
INVERTER HOSE INLET HH	1	\$ 84.60	\$ 84.60	X
INVERTER HOSE OUTLET HH	1	\$ 60.50	\$ 60.50	X
INVERTER WATER PUMP ELECTRIC Dam	1	\$ 820.65	\$ 820.65	✓
GEARBOX ACTUATOR SHIFT CONTROL Dam HH	1	\$ 1,980.30	\$ 1,980.30	X
LOUVER SUB - ASSY COWL TOPVENTILATOR HH	1	\$ 738.40	\$ 738.40	X
BATTERY TRAY BRACKET st	1	\$ 72.80	\$ 72.80	✓
FLOG LAMP WIRE (LH) HH	1	\$ 118.50	\$ 118.50	X
HYBRID WATER HOSE PUMP INLET mostly broken	1	\$ 78.80	\$ 78.80	✓
HYBRID HOSE RADIATOR INLET cut	1	\$ 69.60	\$ 69.60	✓
REAR SAFETY BELT (LH/RH) actuated 995.10 x 2 = 1990.20	2	\$ 1,182.84	\$ 2,365.67	✓
STEERING ANGLE ASSY actuated 986.00	1	\$ 1,495.50	\$ 1,495.50	✓
Sensor				
SUB TOTAL			\$ 24,877.88	
LESS 20% 25% 15014.19			\$ 4,975.58	
DISCOUNTED TOTAL			\$ 19,902.31	
11260.64				
BATTERY damaged SN 1	1	\$ 310.53	\$ 310.53	160/-
160.00				
SUB TOTAL			\$ 310.53	160/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after