

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4746E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PRIG4 COVER REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
10	PRIVC BUMPER PIECE	NOT NECESSARY	22.00	-
1	PRIG4 FILLER-REAR BUMPER	NOT NECESSARY	148.40	-
1	PRIG4 GUARD-REAR BUMPER C	NOT NECESSARY	552.60	-
1	PRIG4 MLDG ASSY BODY ROCK	TO REPAIR SEE LABOUR	290.00	-
1	PRIG4 WHEEL DISC	CUT	1,555.10	1,555.10
	LESS 25% DISCOUNT		-756.88	-388.78
			2,270.62	1,166.32
	NETT ITEMS			
1	APP LOGO REAR BONNET CTPL (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-	-8.00
			80.00	72.00
	SPECIAL NETT ITEMS			
1	PRIVC/IONIQ WL 195/65R15 (SN)	NOT NECESSARY	216.00	-
			216.00	-
	<u>LABOUR</u>			
	PANEL BEATING (REPAIR RR FENDER RH). INCLUSIVE OF THE REPAIR OF PRIG4 COVER REAR BUMPER AND PRIG4 MLDG ASSY BODY ROCK.		800.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		750.00	600.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
	ADJUST FRONT WHEEL ALIGNMENT.		80.00	60.00
			1,810.00	1,040.00
	GRAND TOTAL		4,376.62	2,278.32

RECOMMENDED COST OF LUMP SUM REPAIRS	1,800.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC20011375/Eqf3e2





Report Ref No. NS/INC20011375/Eqf3e2



**CHEN TSUE YEE** 

**Automotive Assessor** 



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser