



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN ANG MOEY, DIANA	Cust No/Name LCV09029/TAN ANG MOEY, DIANA
BLK 20 BEDOK SOUTH ROAD	Reg No/Reg Date SMK610C / 28/03/201
#22-35	Date In/Mileage / 0
SINGAPORE 460020	Chassis No KNAF3416MK5030001
Contact No	Engine No G4FGJH719401
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV09029	CRDVCH	20/10/2020/ 14:09	BLC	442 / CocoLu	22971
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000					3600 4000.00
RENEW FRT BUMPER, FRT FENDER RH, FRT DOOR RH, REAR DOOR RH		450.			
REAR FENDER RH, REAR BUMPER, FRT SUPPORT PANEL, WINDMIRROR RH					
REPAIR SIDE SILL RH					
E PNT88000					Xnn 100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR					
M SUNDRY					Xnn ? 80.00
TOP UP AIRCON GAS					at 50.00
M SUNDRY					
FRT NUMBER PLATE WITH FRAME					
E PNT98000					2100 2800.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, FRT DOOR RH, REAR DOOR RH		350.			
SIDE SILL RH, REAR FENDER RH, REAR BUMPER, WINDMIRROR RH					
E PNT88000					✓ 120.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS					
E PNT88000					✓ 120.00
REMOVE & INSTALL REAR DOOR TRIMS AND GLASS					
E PNT88000					✓ 240.00
REMOVE & INSTALL REAR WINDSCREEN					
M SUNDRY					✓ 80.00
APPLY SEALANT FOR REAR WINDSCREEN					
E PNT88000					160 200.00
REMOVE & INSTALL REAR QUATER GLASS					
M SUNDRY					nec 40.00
APPLY SEALANT FOR REAR QUATER GLASS					
A 90000001					✓ 30.00
CHECK WIRING & ELECTRICAL SYSTEM					
A 10028901					✓ 120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST					
USING HI-SCAN PRO TEST					
B WHEELALIGNMENT					✓ 120.00
To Conduct Computerize Full Wheel Alignment					
M SUNDRY					9/ 30.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent damage to the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN ANG MOEY, DIANA	Cust No/Name LCV09029/TAN ANG MOEY, DIANA
BLK 20 BEDOK SOUTH ROAD	Reg No/Reg Date SMK610C / 28/03/201
#22-35	Date In/Mileage / 0
SINGAPORE 460020	Chassis No KNAF3416MK5030001
Contact No	Engine No G4FGJH719401
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV09029	CRDVCH	20/10/2020/ 14:09	BLC	442 / Cocolu	22971			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TRANSFER REAR RIGHT RIM								✓ 160.00
E PNT88000								✓ 120.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS AND REAR FENDER INNER TRIMS								2 400.00
M SUNDRY								✓ 20.00
APPLY SEALANT FOR ACCIDENT PORTION								
A 90000001								
RENEW FRONT & REAR UNDER CARRIAGE.								
M SUNDRY								
Sundry								
M COVER-FR BUMPER					1.00	633.00	00.00	de 633.00
M GRILLE-FRONT BUMPER					1.00	485.00	00.00	cra 485.00
M COVER-FR BUMPER FOG LAMP,RH					1.00	15.00	00.00	nn 15.00
M LAMP ASSY-FRONT FOG,RH					1.00	303.00	00.00	X 303.00
M GRILLE ASSY-RADIATOR					1.00	328.00	00.00	cra 328.00
M MOULDING-FRONT BUMPER,RH					1.00	216.00	00.00	cut 216.00
M LAMP ASSY-SIDE REPEATER,RH					1.00	143.00	00.00	nn 143.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	00.00	de 84.00
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	00.00	nn 22.00
M PANEL-FENDER,RH					1.00	430.00	00.00	bt 430.00
M INSULATOR-FENDER RH					1.00	27.00	00.00	de 27.00
M BEAM COMPLETE-FR BUMPER					1.00	497.00	00.00	nn 497.00
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	00.00	nn 675.00
M LAMP ASSY-HEAD,RH					1.00	2210.00	00.00	nn 2210.00
M PANEL ASSY-FRONT DOOR,RH					1.00	1277.00	00.00	bt 1277.00
M HINGE ASSY-FRONT DOOR,RH					1.00	30.00	00.00	nn 30.00
M HINGE ASSY-DOOR LOWER,RH					1.00	27.00	00.00	nn 27.00
M MIRROR ASSY-OUTSIDE RR VIEW,RH					1.00	559.00	00.00	cut 559.00
M MOULDING ASSY-FRT DR FRAME,RH					1.00	72.00	00.00	nn 72.00
M HANDLE ASSY-DOOR OUTSIDE,RH					1.00	164.00	00.00	cut 164.00
M COVER-FR DR O/S HDL RH					1.00	14.00	00.00	cut 14.00
M BASE ASSY-FR DR O/S HANDLE RH					1.00	52.00	00.00	X 52.00
M LATCH ASSY-FRONT DOOR,RH					1.00	400.00	00.00	nn 400.00
M PANEL ASSY-FRONT DR MODULE,RH					1.00	241.00	00.00	nn 241.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
TAN ANG MOEY, DIANA	Cust No/Name LCV09029/TAN ANG MOEY, DIANA
BLK 20 BEDOK SOUTH ROAD	Reg No/Reg Date SMK610C / 28/03/201
#22-35	Date In/Mileage / 0
SINGAPORE 460020	Chassis No KNAF3416MK5030001
Contact No	Engine No G4FGJH719401
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV09029	CRDVCH	20/10/2020/ 14:09	BLC	442 / CocoLu	22971

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL ASSY-REAR DOOR,RH	1.00	1377.00	00.00	1377.00
M MOULDING ASSY-RR DR FRAME,RH	1.00	50.00	00.00	50.00
M BASE ASSY-FR DR O/S HANDLE RH	1.00	52.00	00.00	52.00
M LATCH ASSY-REAR DOOR,RH	1.00	309.00	00.00	309.00
M BLACK TAPE-FR DR RR,RH	1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FR,RH	1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FRAME RR OTR,	1.00	8.00	00.00	8.00
M PANEL ASSY-QUARTER OUTER,RH	1.00	1349.00	00.00	1349.00
M FILM-ANTI CHIPPG RH	1.00	27.00	00.00	27.00
M COVER-RR BUMPER	1.00	651.00	00.00	651.00
M BRACKET-ASSY RR BPR SIDE UPK,R	1.00	31.00	00.00	31.00
M GUARD-REAR WHEEL,RH	1.00	75.00	00.00	75.00
M GLASS & MOULDING ASSY-QUARTER	1.00	252.00	00.00	252.00
M WHEEL ASSY-ALUMINIUM	1.00	926.00	00.00	926.00
M HUB & BEARING ASSY-RR	1.00	437.00	00.00	437.00
M SHOCK ABSORBER ASSY-REAR	1.00	231.00	00.00	231.00
M TORSION AXLE COMPLETE	1.00	1031.00	00.00	1031.00
M HUB ASSY-FR WHEEL	1.00	436.00	00.00	436.00
M ORNAMENT-KIA NO.115	1.00	32.00	00.00	32.00

SURVEYOR NAME: Tan Jia 9249544SURVEYOR SIGNATURE: [Signature]DATE: 20/10/2020 2:45pmREMARKS: Not in House, Ex: to be advise.Resurvey before paint, Tan Jia 14 days

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before paint spray painting

- Confirm & accepted by:
- Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

7% GST on **Nett** 25,034.00
 1752.38
Total Payable 26,786.38

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of the rubber seal or other repair requiring the removal of the windscreen.