

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011382/UYD3Q2

Date: 04/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00111652000
Claimant Vehicle No :	SJH9067M	Insured Vehicle No :	SMU4827R
Date of Loss:	15/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D203902/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH9067M	Engine No:	L13A4083794
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61074575
Reg. Date:	27/08/2008 (Man. Year: 2008)	Odometer:	118560 km
Colour:	Black		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,824.16	1,339.28	484.88	26.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	1,310.00	410.00	23.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,544.16	2,649.28	894.88	25.25
Approved Total (Overridden) (\$\$)		2,100.00		
(\$\$)	3,544.16	2,100.00	1,444.16	40.75
+ GST 7.00/7.00% (\$\$)	248.09	147.00	101.09	40.75
Nett Amount (\$\$)	3,792.25	2,247.00	1,545.25	40.75

INSPECTION

Date of Assignment:	20/10/2020	
Date Inspected:	21/10/2020 Inspected At:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2020)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH9067M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BONNET HINGES	Repair	70.00 FL	*- FL
2	1		*FRONT BONNET LOCK	Not Necessary	95.10 FL	*- FL
3	1		*FRONT BONNET	Repair	426.60 FL	*- FL
4	1		*FRONT FENDER -LH	Badly Dented	372.60 FL	*372.60 FL
5	1		*FRONT FENDER DUST COVER -LH	Torn	69.40 FL	*69.40 FL
6	1		*SET FRONT FENDER DUST COVER CLIPSE-LH	Necessary	33.00 FL	*30.00 FL
7	1		*FRONT HEADLAMP -LH	Holder Cracked	588.00 FL	*588.00 FL
8	1		*FRONT HEADLAMP LOWER BRACKET	Cracked	45.10 FL	*45.10 FL
9	1		*FRONT BUMPER	Distorted	548.20 FL	*548.20 FL
10	1		*FRONT BUMPER SIDE RETAINER -LH	Bent	32.20 FL	*20.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,280.20	1,674.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	456.04	334.82

Total Parts (\$\$)	1,824.16	1,339.28
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	850.00	580.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	30.00
4	TO SPRAY PAINTING	New	750.00	680.00
Gross Labour Cost (\$\$)			1,720.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >