

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPQBE

19/10/2020

Jia Le.

Accident date: 17/10/2020

Estimated repair cost for vehicle no: SLK5521E TOYOTA COROLLA ALTIS CLASSIC 17'

CHASSIS: MR053REH104558420

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Buellered</i>		\$685.80 ✓
2	2	Rear Boot Lid Hinge <i>xhe m</i>	\$77.80	\$155.60 +
3	1	Rear Boot Lid Emblem Logo <i>Nu</i>		\$66.70 ✓
4	1	Rear Boot Lid Lock <i>Dangd</i>		\$382.00 ✓ 255
5	1	Rear Boot Lid Weatherstrip <i>cut</i>		\$166.40 ✓
6	1	Rear Boot Lid Reverse Camera <i>xhe m</i>		\$450.00 +
7	1	Rear Boot Lid Number Plate <i>xhe m</i>		\$50.00 +.
8	1	Rear Boot Lid Center Moulding <i>xhe m</i>		\$307.90 +.
9	2	Rear Boot Lid Side Reflector <i>cut</i>	\$280.50	\$561.00 ✓
10	2	Rear Tail Lamp <i>cut</i>	\$463.10	\$926.20 ✓ 770
11	2	Rear Tail Lamp Clip <i>Nu</i>	\$8.00	\$16.00 ✓
12	2	Rear Tail Lamp Panel <i>xhe m</i>	\$176.90	\$353.80 x.
13	1	Rear Bumper <i>Dented</i>		\$482.00 ✓
14	10	Rear Bumper Clip <i>m</i>	\$6.50	\$65.00 ✓ 30
15	2	Rear Bumper Side Retainer <i>Nu</i>	\$104.50	\$209.00 ✓
16	2	Rear Bumper Side Reflector <i>LH cut</i>	\$45.10	\$90.20 ✓ 45.10
17	1	Rear Bumper Reverse Sensor (Special Nett) <i>Dangd</i>		\$350.00 ✓ 200/su
18	1	Rear Bumper Reinforcement <i>Dented</i>		\$381.70 ✓
19	2	Rear Fender <i>Repair</i>	\$972.45	\$1,944.90 x.
20	2	Rear Fender Inner Trim Board <i>Nu m</i>	\$415.10	\$830.20 +
21	16	Rear L/H Fender Inner Trim Board Clip <i>Nu m</i>	\$6.50	\$104.00 +.
22	1	Rear End Panel <i>Dented</i>		\$581.10 ✓
23	1	Rear End Panel Top Garnish <i>couled</i>		\$229.40 ✓

4479.20.

Subtotal :- \$9,388.90

335940

SX:200

Labour charges

To remove & refit cushion & trim board

~~\$280.00~~ 60

To remove & refit rear reverse sensor

~~\$100.00~~ 50

To remove & refit reverse camera

~~\$180.00~~ 50

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 80

Towing fee

2070

\$150.00 X

Panel beating

~~\$1,600.00~~ 90

Spray painting

~~\$1,400.00~~ 90

Subtotal :- \$3,960.00

Total:- \$13,348.90

total 5629.40

L/S: A.S.K.

26 Days.

A.S.K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: