

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT120011386/4v43

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ8788M

at Workshop m/s

FA lbi

of

Insured:

GBF9999D

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

61k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5
20

days

Res.:

Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5706

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLJ8788M

Yr Regn:

12 16

Type: M/Caf / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Toyota Corolla Altis

Colour

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

105230

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053 RGH104551148

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Drm / STD A/Rim or

Tyre Size:

F:

215/45-2R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

17/10/20

D.O.I.

21/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

07/10/20LTA #47162 Nil (1383)31/10/20 4/5 #4100 Confirmed with Ray (Red 3965.98, 49%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 2/11/20-TypistDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

TOTAL

Report Format: MerimenLump Sum H.B. (\$ 4100)

Progressive Car Care Pte Ltd

BLK 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccarcare.com.sg
GST:201006949C RCB NO:201006949C

Not Authorized
N/A
21/10/20
4/5 # 4100
take photo after repair
5 days.

M/S: HUANG ZIYAN
BLK 211C COMPASSVALE LANE #08-230
SINGAPORE 543211

ATTN: CHINA TAIPING

Your Ref No: TP 1020-6109
Claim Type: Third Party
Accident Date: 17/10/2020
TP Veh Reg No: GBB 99 G

Estimate No: EST1506314
Date: 17 Oct 2020
Policy No: PNPV2018-00013678
Veh Reg No: SLJ8788M
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT
Chassis No: MR053REH104551148
Engine No: 1ZR574436
Reg. Date: 01/12/2016

Estimate Repair Cost to Vehicle No :SLJ8788M

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 REAR BOOT <i>506.00</i>	793.20	1 PC	793.20	✓
2 REAR BOOT RUBBER <i>7m</i>	175.80	1 PC	175.80	✓
3 REAR BUMPER LOCK SENSOR <i>11</i>	192.20	1 PC	192.20	X
4 REAR BOOT TOP LOCK <i>7m</i>	399.50	1 PC	399.50	✓
5 REAR BOOT BOTTOM LOCK <i>11</i>	65.40	1 PC	65.40	X
6 REAR BOOT TOYOTA LOGO <i>2m</i>	61.50	1 PC	61.50	✓
7 REAR BOOT COROLLA WORDING <i>2m</i>	62.40	1 PC	62.40	✓
8 REAR BOOT ALTIS WORDING <i>2m</i>	59.60	1 PC	59.60	✓
9 REAR BOOT INSULATOR CLIP <i>11</i>	5.50	12 PCS	66.00	X
10 REAR BOOT OUTER CHROME <i>11</i>	243.70	1 PC	243.70	X
11 REAR BOOT REFLECTOR - LH <i>11</i>	353.40	1 PC	353.40	X
12 REAR BOOT REFLECTOR - RH <i>11</i>	353.40	1 PC	353.40	X
13 REAR BUMPER <i>Dis</i>	556.40	1 PC	556.40	X
14 REAR BUMPER CLIPS <i>2m</i>	5.50	10 PC	55.00	✓
15 REAR BUMPER SIDE HOLDER - LH <i>11</i>	109.30	1 PC	109.30	X
16 REAR BUMPER SIDE HOLDER - RH <i>but</i>	109.30	1 PC	109.30	✓
17 REAR BUMPER CENTRE RETAINER - LH <i>11</i>	70.40	1 PC	70.40	X
18 REAR BUMPER CENTRE RETAINER - RH <i>but</i>	70.40	1 PC	70.40	✓
19 REAR BUMPER CENTER BRACKET - LH <i>11</i>	68.20	1 PC	68.20	X
20 REAR BUMPER CENTRE BRACKET - RH <i>11</i>	68.20	1 PC	68.20	✓
21 REAR BUMPER REINFORCEMENT <i>Dis</i>	399.50	1 PC	399.50	✓
22 REAR BUMPER SENSOR - LH, RH <i>shield</i>	380.40	1 SET	380.40	✓
23 REAR PANEL <i>506.00</i>	670.00	1 PC	670.00	✓
24 REAR PANEL TOP GARNISH <i>7m</i>	241.90	1 PC	241.90	✓
25 TAIL LAMP ASSY - LH <i>11</i>	379.80	1 PC	379.80	X
26 TAIL LAMP ASSY - RH <i>eng</i>	379.80	1 PC	379.80	✓
27 REAR EXHAUST PIPE <i>11</i>	1,124.90	1 PC	1,124.90	X
28 REAR EXHAUST PIPE TOP PLATE <i>11</i>	105.60	1 PC	105.60	X
29 REAR EXHAUST PIPE MOUNTING <i>11</i>	48.70	3 PC	146.10	X
			7,761.30	
Less 25%			1,940.33	5,820.98

Special Net

30 REAR NUMBER PLATE WITH CASING <i>11</i>	35.00	1 SET	35.00	X
			35.00	35.00

Labour

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : HUANG ZIYAN
BLK 211C COMPASSVALE LANE #08-230
SINGAPORE 543211

ATTN: CHINA TAIPING

Your Ref No: TP 1020-6109
Claim Type: Third Party
Accident Date: 17/10/2020
TP Veh Reg No: GBB 99 G

Estimate No: EST1506314
Date: 17 Oct 2020
Policy No: PNPV2018-00013678
Veh Reg No: SLJ8788M
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT
Chassis No: MR053REH104551148
Engine No: 1ZR574436
Reg. Date: 01/12/2016

Estimate Repair Cost to Vehicle No :SLJ8788M

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
31 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	900.00	1 JOB	900.00	800
32 TO RESPRAY PAINT ON ACCIDENT PORTIONS	900.00	1 JOB	900.00	850
33 TO CHECK WIRING	50.00	1 JOB	50.00	20
34 TO TRANSFER REAR BUMPER SENSOR	100.00	1 JOB	100.00	50
35 TO TUFF-KOTE	60.00	1 JOB	60.00	1
36 TO REMOVE, REFIX REAR GARNISH	100.00	1 JOB	100.00	80
37 TO REMOVE, REPLACE REAR EXHAUST PIPE	100.00	1 JOB	100.00	2
			2,210.00	2,210.00
Total				S\$ 8,065.98
Add GST @ 7%				564.62
Total Amount Payable				S\$ 8,630.60

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND SIX HUNDRED THIRTY AND CENTS SIXTY ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4413
252
P-330975
K-1860.00
5169.75
202
4135