

SGP 8511Y / OD / CHINA TAI PING

Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Fri 23/10/2020 2:15 PM

To: Brian Eng Kwok Long <EngKwokLong@goldbell.com.sg>

Cc: Ramesh S/O Somasundrem <Ramesh@goldbell.com.sg>; SUR <sur@lkkauto.com>

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGP 8511Y (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)