

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD660D**AAD2010-069***Not Authored*
11 Sep @ 4300h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

19 OCT 2020**SHD660D**

VF1ABL15AUC283410

RENAULT

LATITUDE

15/10/2020

LONPAC

01/03/2017

PART		LIST	
1	BUMPER COVER FRT	CM 747.20	✓
1	BUMPER BEAM FRT	R 663.70	X
1	BUMPER SPOILER FRT	DIR 344.70	✓
1	BUMPER ABSORBER FRT	CM 394.68	✓
1	BUMPER BRACKET FRT RH (Headlamp Lower)	CM 116.47	✓
1	BUMPER RETAINER FRT RH	CM 101.40	✓
1	BUMPER SUPPORT FRT	SL 10.70	X
1	RADIATOR GRILLE	mgum 969.90	✓
1	RADIATOR GRILLE FRAME	CM 686.00	✓
1	RADIATOR GRILLE BADGE "RENAULT"	na 225.36	✓
1	BUMPER GRILLE LOWER FRT	SL 147.00	X
1	BUMPER FOG LAMP GRILLE RH	mit 207.21	✓
1	HEADLAMP RH	mt/cm 743.60	✓
1	HEADLAMP PANEL FRT RH	R 128.30	X
1	FENDER PANEL FRT RH	R 437.10	X
1	BUMPER UNDERTRAY FRT	SL 292.50	X
1	SUBFRAME OUTER FRT	SL 1,094.20	X
1	WHEELARCH FRT RH	CM 191.40	✓
TOTAL		\$ 7,501.42	
10%		\$ 750.14	
		\$ 6,751.28	

Special Nett

1SET	BUMPER CLIP FRT	\$	na 90.00	66/na
1	BUMPER BRACKET CLIP FRT	\$	na 75.00	X

Trans-cab Auto Services Pte Ltd**AAD2010-069**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD660D

1 BUMPER SUPPORT CLIP FRT	\$	nn	10.00	X
1SET BUMPER RETAINER CLIP FRT	\$	nn	70.00	X
1SET BUMPER GRILLE LOWER CLIP	\$	nn	70.00	X
1 BUMPER FOG LAMP GRILLE CLIP	\$	nn	65.00	X
1 BUMPER SPOILER CLIP	\$	nn	60.00	X
1SET WHEELARCH CLIP FRT	\$	nn	80.00	✓
1SET RADIATOR GRILLE SCREW	\$	nn	60.00	X
1SET RADIATOR GRILLE FRAME CLIP L70Y	\$	nn	65.00	✓
1 TOWING FEE	\$	nn	170.00	X

TOTAL \$ 520.00**TOTAL PARTS \$ 7,271.28****LABOUR**

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ nn 380.00 X

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 1,800.00 500/

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 20/

To rust-proofing and apply undercoat of the affected areas.

\$ nn 250.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

Trans-cab Auto Services Pte Ltd

AAD2010-069

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD660D

To remove and refit battery, electrical wiring, fuse box and relay to enable repair.

\$ *na* 450.00 X

Putty and spray painting of the affected portion.

\$ 1,800.00 *4401*

TOTAL \$ 5,620.00

Over All Total \$ 12,891.28

Repair Days (LUMP SUM)

~~28~~ DAYS

3 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: