新合利服務公司

Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20 Singapore 159761

Tel: 6278 2482 Fax: 6271 9802 Email: sinhuplee@gmail.com Reg. No. 083995/00E

6 October 2020

Attn: Motor Claim Department AIG Asia Pacific Insurance Pte Ltd AIG Building 78 Shenton Way #07-16 Singapore 079120

Wong Kim Seow c/o Sin Hup Lee Service Co. Block 1005 Bukit Merah Lane 2 #01-20 Singapore 159761

Dear Sir/Ms,

RE: Road Traffic Accident on 18 September 2020 along Chapel Road, involving vehicle SK3004T/SJJ6304M

Quotation for Repair Vehicle No: SJJ6304M (Third Party Claim)

Quantity	List Item		Price
1	Front Bumper de / Front Head Lamp LH 3Ce /	\$	465.00
1	Front Head Lamp LH 3C	\$	718.00
1	Front Fender LH	\$	310.00
1	Front Fender Cowling Cod /	\$	118.00
1	Front Door LH repoir	\$	568.00
1	Front Door Moulding 🖍	\$	55.00
1	Front Door Protector 🗡	\$	38.00
1	Side Skirt 🗡	Ś	489.00
1	Tyre Rim S	Ś	180.00
1	Tyre Rim SA / Front Side Bracket Cut /	\$	50.00
		\$	2,991.00
	Less 2	25% \$	747.75
		Ś	2.243.25

Labour

1	To repair, remove & re-fix damaged parts, straighten and realign affected areas		\$ 400 850.00
2	To spray paint work on affected areas		\$ 600 780.00
3	To remove and refix Door Glass Mechanism. Check and test Motor and Centre Locking System		\$ × 200.00
4	To rust proof affected areas		\$ 40 100.00
		Total Amount	\$ 4,173.25

Kindly arrange your surveyor to survey my vehicle. We look forward to hear from you soon. Thank you.

Yours Faithfully Mr Wong 81122116

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUR

Ho Pooloobs

5 days

Ho 29/10/2020@1400

Resny after report