

SK Automobile Pte. Ltd.  
 (Co Reg. No. 201500047H)  
 8 Kaki Bukit Ave 4 #08-45/46  
 Premier@Kaki Bukit S(415875)  
 Tel : 6789 5155 Fax : 6783 5155

TO : INDIA	DATE : 19-Oct-20
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	
<b>OWNER PARTICULAR</b>	
NAME :	<b>VEHICLE DETAILS</b>
ADDRESS :	VEHICLE NO. : SLQ1852U
TEL. NO. :	MODEL / MAKE : SSANGYONG
	CHASSIS NO. : KPT36B1VSGP107615
OWNER INSURANCE : FWD	<b>ACCIDENT DETAIL</b>
POLICY NO. : PNPV2019-00005249-01	DATE : 18-Oct-20
	TIME : 12:25hrs
PERSON INCHARGE :	

QUOTATION SUMMARY PAGE 01

**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR PROTECTOR LH (STICK ON) <i>cut</i>	1	\$ 287.50	\$ 287.50
2	ROCKER SIDE SKIRTING LH <i>cut</i>	1	\$ 498.90	\$ 498.90
3	REAR DOOR LH <i>Repair</i>	1	\$ 3,666.80	\$ 3,666.80
4	REAR DOOR PROTECTOR LH (STICK ON) <i>cut</i>	1	\$ 297.10	\$ 297.10
5	REAR FENDER ARCH GARNISH LH <i>cut</i>	1	\$ 288.70	\$ 288.70
6	REAR FENDER INNER SHIELD LH <i>the m</i>	1	\$ 342.60	\$ 342.60
7	REAR SUSPENSION WHEEL HUB BEARING LH <i>the m</i>	1	\$ 458.40	\$ 458.40
8	REAR 16" SPORT RIM LH <i>cut</i>	1	\$ 1,600.30	\$ 1,600.30
TOTAL PRICE				\$ 7,440.30
LESS -10%				\$ (744.03)
<b>SUB TOTAL PRICE</b>				<b>\$ 6,696.27</b>

1372-20  
1234-98 S-N: 600

**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	ROCKER SIDE SKIRTING CLIPS SET LH <i>the m</i>	1	\$ 80.00	\$ 80.00
2	REAR FENDER ARCH GARNISH CLIPS SET LH <i>the m</i>	1	\$ 60.00	\$ 60.00
3	REAR FENDER INNER SHIELD CLIPS SET LH <i>the m</i>	1	\$ 60.00	\$ 60.00
<b>TOTAL</b>				<b>\$ 200.00</b>

*4 REAR FENDER ARCH GARNISH PROTECTOR (CARBON TYPE) \$150.00*  
*cut* 100

150

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 800.00	300	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 800.00	300	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 105.00	30	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	x	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	x	
TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM LH TO FACILITATE REPAIR WITH CHECKING	\$ 280.00	x	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH TO PERFORM FACILITATE REPAIRS	\$ 350.00	x	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 100.00	80	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	x	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	x	

**TOTAL**      \$ 2,955.00

710

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	6,896.27
TOTAL LABOUR COST	:	\$	2,955.00
TOTAL REPAIR COST	:	\$	<u>9,851.27</u>

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM : Adrian Lj

CONTACT NUMBER : 2/5 21/10/20

FAX NUMBER : 03 Days

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

EXCESS : total: 2694.98  
4/5: 2150

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: