

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SLR4168L

OUR REF.: SLW8542L

TO: AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 4/8/2020
FROM: Eryx Tan
FAX: 6452 5333
CONTACT: 8138 7188
MAKE & MODEL: HONDA VEZEL 1.5X CVT
CHASSIS NO.: RU11233003
ENGINE NO.: L15B4433010
YEAR MADE: 2018
ACCIDENT DATE: 19 October 2020

*Not Authorised
L1 Imp @ 2400h
Recovery After Paint
4- days*

ESTIMATE FOR VEHICLE NO.:

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAIL GATE <i>1050</i>		1	\$ <i>10</i> ✓ 1,950.00
2	TAIL GATE GLASS MOULDING		1	\$ <i>10</i> ✓ 120.00
3	WEATHERSTRIP, TAILGATE		1	\$ <i>10</i> X 150.00
4	TAIL GATE HINGE		2	\$ <i>10</i> X 160.00
5	TAILGATE SPOILER		1	\$ <i>10</i> X 250.00
6	TAIL GATE INNER TRIM		1	\$ <i>10</i> X 480.00
7	TAIL GATE UPPER LINING		1	\$ <i>10</i> X 120.00
8	TAIL GATE SIDE INNER LINING LH		1	\$ <i>10</i> X 50.00
9	TAIL GATE SIDE INNER LINING RH		1	\$ <i>10</i> X 50.00
0	TAIL GATE EMBLEM "VEZEL"		1	\$ <i>10</i> ✓ 50.00
1	TAIL GATE EMBLEM "HONDA" LOGO		1	\$ <i>10</i> X 20.00
	TAIL GATE LAMP LH		1	\$ <i>10</i> X 500.00
	TAIL GATE LAMP RH		1	\$ <i>10</i> X 500.00
	REAR BUMPER <i>762.00</i>		1	\$ <i>10</i> ✓ 1,000.00
	REAR BUMPER REFLECTOR LH		1	\$ <i>10</i> X 150.00
	REAR BUMPER REFLECTOR RH		1	\$ <i>10</i> X 150.00
	REAR BUMPER CORNER PANEL RH		1	\$ <i>10</i> X 380.00
	REAR BUMPER CORNER PANEL LH		1	\$ <i>10</i> X 380.00 X
	REAR BUMPER CORNER PANEL INNER LINING RH		1	\$ <i>10</i> X 250.00
	REAR BUMPER CORNER PANEL INNER LINING LH		1	\$ <i>10</i> X 250.00
	REAR BUMPER CORNER COVER BRACKET RH		1	\$ <i>10</i> X 75.00
	REAR BUMPER CORNER COVER BRACKET LH		1	\$ <i>10</i> X 75.00
	REAR BUMPER CROSS MEMBER		1	\$ <i>10</i> X 200.00
	REAR BUMPER CLIP		1	\$ <i>10</i> ✓ 90.00 <i>50%</i>
	REAR BUMPER UNDERCOVER		1	\$ <i>10</i> X 200.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FENDER INNER LINER RH	1	\$	Pr	X	100.00
FENDER INNER LINER LH	1	\$	Pr	✓	100.00
WHEEL ARCH PROTECTOR RH	1	\$	Pr	X	150.00
WHEEL ARCH PROTECTOR LH	1	\$	Pr	Pr	150.00 X
TAIL LAMP RH	1	\$	Pr	X	500.00
TAIL LAMP LH	1	\$	Pr	X	500.00
REAR END PANEL	1	\$	Pr	Pr	650.00 X
REAR END PANEL TOP GARNISH	1	\$	Pr	Pr	85.00 X
TOTAL:	\$				9,835.00
LESS 20%:	\$				(1,967.00)
PARTS TOTAL:	\$				7,868.00

SPECIAL NETT

REAR NUMBER PLATE & HOLDER	1	\$	Pr	X	50.00
BODY SEALANT	1	\$	Pr	Pr	50.00 X
TAIL GATE SEALANT	1	\$	Pr	Pr	80.00
REAR BUMPER SENSOR	1	\$	Pr	Pr	250.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	7	400h	1,600.00
TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPAIR	\$	60h		150.00
TO REMOVE & INSTALL TAILGATE GLASS	\$	120h		180.00
TO APPLY ANTI RUST COATING	\$	30h		80.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	15h		100.00
TO REMOVE & INSTALL REVERSE SENSOR	\$	50h		80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	500h		1,000.00
TOTAL:	\$			11,488.00
7% GST:	\$			804.16
GRAND TOTAL:	\$			12,292.16