

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

Model : **Honda Fit 1.3 GF**Registraion No : **SMM 827 J**Chassis No: **GK33415390**Year of Manufacturing: **2019**

S/No	Qty	Items	Unit Price	Amount
1	1	Bonnet <i>one</i>	\$ 987.65	\$ 987.65 551.5
2	1	Bonnet Lock X	\$ 157.89	\$ 157.89
3	1	Bonnet Insulator X	\$ -	\$ -
4	4	Bonnet Outer Rubber X <i>BR</i>	\$ 35.45	\$ 141.80
5	1	Front Bumper <i>BR</i>	\$ 744.86	\$ 744.86 517.7
6	1	Front Bumper Retainer (RH) X <i>SNN</i>	\$ 36.47	\$ 36.47
7	1	Front Bumper Bracket (RH) X <i>SNN</i>	\$ 41.52	\$ 41.52
8	1	Front Bumper Fog Light Garnish (RH) X <i>SNN</i>	\$ 51.23	\$ 51.23
9	1	Front Bumper Reinforcement X	\$ 385.24	\$ 385.24
10	1	Front Bumper Radiator Grille Chrome <i>SNN</i>	\$ 541.23	\$ 541.23
11	1	Headlight (RH) <i>CRA</i>	\$ 754.88	\$ 754.88 ✓
12	1	Front Fender (RH) <i>repair</i> X	\$ 665.47	\$ 665.47
				\$ 4,508.24 1824.08
				-20% \$ 901.65
Total for spare parts				\$ 3,606.59 1459.26

Special Nett

1	10	Front Bumper Clip <i>MC</i>	\$ 5.00	\$ 50.00 30
2	1	Headlight Clip set <i>SNN</i>	\$ 30.00	\$ 30.00
3	1	Front No.Plates X	\$ 50.00	\$ 50.00
4	1	Front Windscreen Sealant X <i>SNN</i>	\$ 75.00	\$ 75.00

Total for SP \$ 205.00**Sub-Total for Parts : \$ 3,811.59****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	800.00 400
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,000.00 600
3		Apply rust proofing on the adjacent panels	\$	50.00 X
4		To supply under coating / putty on parts replaced	\$	50.00 X
5		To perform water seepage test after repair	\$	80.00 X
6		To check wiring and lighting system	\$	80.00 30
7		Remove and refit front windscreen	\$	150.00 X
TOTAL AMOUNT :			\$	<u>2,210.00</u> 1030
OVERALL COST:			\$	<u>6,021.59</u>

4 Days .

Temporary Repair.

After we get photos.

Good Deal

21/10/2020

2519.26

-20%: 2000