



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20011417/Uyf3e2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 17-11-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 9445Y	Veh. Inspected	SJS 97C
Policy No.		Coverage (\$)	0.00
Claim No.	C10007629/JM	Excess (\$)	0.00
Assign From	ABIGAIL CHOO	Assign Date	21/10/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053BK4107043093	Colour	WHITE
Odometer	185540	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	PIRELLI	6 mm
L/H Front Tyre	215/60 R16	PIRELLI	6 mm
R/H Rear Tyre	215/60 R16	PIRELLI	6 mm
L/H Rear Tyre	215/60 R16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/10/2020	Inspection Date	21/10/2020
Survey held at	SIANG HUI MOTOR WORKS BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------