

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

20/10/2020 19:23

JOB-NO: 50112885

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA8041D

TRANS: AUTO

CHASSIS: KMHLB41UMGU093520

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU650737

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	700.00	0.00	700.00		Y	300
2 SUNDRIES	1.00	50.00	0.00	50.00		Y	20.20
3 RUST PROOFING	1.00	80.00	0.00	80.00		Y	x
4 DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	1.00	180.00	0.00	180.00		Y	x
5 R&R REVERSE SENSOR	1.00	80.00	0.00	80.00		Y	30
6 R&R SPARE TYRE & CARPET & TRIM & BOARD	1.00	150.00	0.00	150.00		Y	x
7 R&R REAR EXHAUST PIPE & MUFFLER LH	1.00	150.00	0.00	150.00		Y	x
8 RESPRAY REVERSE SENSOR SET	1.00	80.00	0.00	80.00		Y	40
9 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
10 RESPRAY REAR BUMPER DIFFUSER	1.00	200.00	0.00	200.00		Y	100
11 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	200
12 RESPRAY BOOTLID	1.00	250.00	0.00	250.00		Y	x
13 RESPRAY BOOTLID OUTER GARNISH	1.00	200.00	0.00	200.00		Y	x
14 RESPRAY REAR FENDER RH	1.00	250.00	0.00	250.00		Y	x
TOTAL:		2,870.00	0.00	2,870.00			
<u>MATERIALS</u>							
1 REAR BUMPER	1.00	599.68	119.94	479.74	L	Y	de
2 REAR BUMPER DIFFUSER	1.00	228.40	45.68	182.72	L	Y	de
3 REAR BUMPER REFLECTOR LH	1.00	53.85	10.77	43.08	L	Y	x
4 REAR BUMPER RETAINER LH	1.00	48.32	9.66	38.66	L	Y	x
5 REAR BUMPER RETAINER RH	1.00	48.32	9.66	38.66	L	Y	x
6 REAR BUMPER REINFORCEMENT SPONGE	1.00	89.62	17.92	71.70	L	Y	cur
7 REAR BUMPER REINFORCEMENT	1.00	484.40	96.88	387.52	L	Y	cur
8 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	118.63	23.73	94.90	L	Y	ht
9 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	118.63	23.73	94.90	L	Y	x
10 REPAIR BOOTLID OUTER GARNISH	1.00	774.50	154.90	619.60	L	Y	x
11 BOOTLID EMBLEM-CRDI	1.00	52.67	10.53	42.14	L	Y	x
12 BOOTLID EMBLEM-I40	1.00	48.55	9.71	38.84	L	Y	x
13 TAIL LAMP RH	1.00	697.80	139.56	558.24	L	Y	x
14 BOOTLID WEATHERSTRIP	1.00	198.56	39.71	158.85	L	Y	x
15 REAR EXHAUST PIPE & MUFFLER LH	1.00	967.22	193.44	773.78	L	Y	x
16 REAR EXHAUST PIPE & MUFFLER GASKET LH	1.00	39.45	7.89	31.56	L	Y	x

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
17 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	<u>new</u>
18 REAR BUMPER RUBBER PROTECTOR PAD	1.00	120.00	0.00	120.00	S	Y	<u>100 new</u>
19 REAR BUMPER REVERSE SENSOR SET	1.00	230.00	0.00	230.00	S	Y	<u>200 new</u>
20 REPAIR REAR END PANEL	1.00	0.00	0.00	0.00	S	Y	<u>Ry</u>
21 REPAIR BOOTLID	1.00	0.00	0.00	0.00	S	Y	<u>x</u>
22 REPAIR REAR FENDER RH	1.00	0.00	0.00	0.00	S	Y	<u>x</u>
TOTAL:		4,953.60	913.71	4,039.89			
TOTAL PARTS & LABOUR:		7,823.60	913.71	6,909.89			

EXCESS/LOADING:S\$ 0.00

No. Of Day: 03

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 21 / 10 / 20

SURVEYED BY: Tan

Tan

CONTACT NO: 9741544 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: