

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW357U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO RENEW REAR END PANEL	1170.00	585.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	750.00	500.00
3	ZZ/003	REMOVE AND INSTALL BOTH RR COMB LAMP TO FACILITATE RR BUMPER REPLACEMENT	48.00	48.00
4	ZZ/004	RENEW REVERSE SENSOR	110.00	110.00
TOTAL LABOUR CHARGES			2078.00	1243.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW357U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 REAR BUMPER	85022-4EA0H	796.70		OK
SUB TOTAL		796.70	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		159.34	0.00	0.00
GRAND TOTAL		637.36	0.00	0.00
OVERALL TOTAL		637.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKW357U

NETT ITEM	796.70
LESS 20.00%)	159.34
NETT AMOUNT	637.36
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	1243.00
TOTAL SPARE PARTS CHARGES	637.36
TOTAL CHARGES	1880.36
ADD 7 % GST	131.63
GRAND TOTAL	2011.99

1880.36