



Your Ref : 1202000021292

Date: 12th Nov 2020

Our Ref : CS4/FWD20011424/Kyf3e2

M/s FWD Singapore Pte Ltd

6 Temasek Boulevard

#18-01 Suntec Tower 4

Singapore 038986

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGZ 7677G
ACCIDENT ON 15/10/2020**

Instruction was received to inspect the vehicle Reg. No. SGZ 7677G. The inspection was conducted on 21/10/2020 at the premises of M/s Ah Lim Motor Company, 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, Singapore 568047.

The following vehicle information was recorded:

Registration Number	: SGZ 7677G
Make/Model	: Toyota Vios E Auto
Year of Registration	: 2007
Body Colour	: Metallic Blue
Chassis Number	: MR053HY9305038853
Engine Capacity	: 1497 cc

The vehicle caught fire after collision on the front rh portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 15,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 8,697.00)
Nett Liability	<u>S\$ 6,303.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.