

CARIS AUTOWORKS PTE LTD
160 SIN MING DRIVE
#05-03 SIN MING AUTOCITY
SINGAPORE 575722
(COMPANY REGISTRATION NO: 201825799E)
TEL: 62589831
FAX: 62585349

Kenrick
96910663

Not Authored
Resurvey B4 pain
2 days

221784

ESTIMATE REPAIR COST TO HONDA (CIVIC) REG NO : SMF 3835 C

			S\$
1 PC	BUMPER (FRONT)	579.90	BT/CM 579.90 ✓
1 PC	BUMPER REINFORCEMENT (FRONT)		n 377.90 X
1 PC	BUMPER BRACKET (FRONT RIGHT)		001 10.40 ✓
1 PC	BUMPER FOG LAMP (FRONT RIGHT)		n 305.90 X
1 PC	BUMPER FOG LAMP GARNISH (FRONT RIGHT)		CM 19.70 ✓
1 PC	HEADLAMP (FRONT RIGHT)	1299.80	CM 1299.80 ✓

TOTAL 2593.60

LESS 20%

518.72

TOTAL 2074.88

LABOUR & MISC CHARGES

PANEL KNOCKING
SPRAY PAINTING
WHEEL ALIGNMENT (COMPUTRISED)
BODY CLIPS
WIRE CHECKING & DIAGNOSTIC

600.00 20d
800.00 22d
nn 100.00 X
nn 50.00 ✓
nn 80.00 X

TOTAL 3704.88

CARIS AUTOWORKS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



[Handwritten signature]

CARIS AUTOWORKS PTE LTD
160 SIN MING DRIVE
#05-03 SIN MING AUTOCITY
SINGAPORE 575722
(COMPANY REGISTRATION NO: 200923135D)
TEL: 62589831
FAX: 62585349

ESTIMATE REPAIR COST TO HONDA (CIVIC) REG NO : SMF 3835 C

SUPPLEMENTARY PARTS

1 PC AIR BAG SENSOR (FRONT RIGHT) *Pt? 275.00 Pd* \$520.00 ✓

208