



Section A - Accident Details

Registration Number	SHB342H
Case Reference Number	TAX/10/20/2041
Registration Date	12/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TEO THOR KIM
Type of Accident	Head to Rear
Accident Date and Time	20/10/2020 10:50 AM
Accident Reported Date and Time	21/10/2020 12:01 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108551
Special Instruction to ARC, if any	REAR PORTION / TP
Prepared Date and Time	21/10/2020 1:33 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$2,016.00	\$380.00
Total Spare Part Cost	\$6,860.42	\$1,133.12
Total Other Cost	\$680.00	\$20.00
TOTAL COST	\$10,401.42	\$1,733.12
Lump Sum Total	\$10,400.00	\$1,750.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / ERGO
ARC / Surveyor Sign Off Date	26/10/2020 11:07 AM	26/10/2020 10:47 AM
Signature		
Remarks	Total number of repair days = 3 days SUP = +1 day.	L/S. After paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2011-0040	Invoice Number	
Quotation Date	04 11 2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$200.00
Total Labour	\$845.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPOILER	\$180.00	\$80.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,016.00	\$380.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$680.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8159147010	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given
		8218347020	WIRE, LUGGAGE ROOM	0.00	\$143.50	0.00	\$0.00	Replace	Not Given
		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check
		5839947030	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given
		5839847050	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given
		6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair
		6935047050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$452.10	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 6365592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 04/11/2020

User ID PohSuan

69321470 10	TAIL GATE LOCK COVER , BACK DOOR	0.00	\$25.30	0.00	\$0.00	Replace	Not Given X
67881470 50	TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$360.70	0.00	\$0.00	Replace	Not Given X
64721470 50C0	TAILGATE BOARD , COVER	0.00	\$24.10	0.00	\$0.00	Replace	Not Given X
67750470 80C0	TAILGATE BOARD ASSY	0.00	\$251.50	0.00	\$0.00	Replace	Not Given X
75441470 90	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace ✓
75442471 30	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace ✓
75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace ✓
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
76085479 16	SPOILER SUB-ASSY, REAR	1.00	\$1,322.10	100.00	\$0.00	Replace	Repair R
81006470 30	LAMP SET, STOP CENTER	0.00	\$186.50	0.00	\$0.00	Replace	Not Given X
58307470 90	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Not Given X
64718470 80C0	END PANEL , COVER, DECK TRIM SERVICE HOLE	0.00	\$47.00	0.00	\$0.00	Replace	Not Given X
64716471 30C0	END PANEL , COVER, DECK TRIM, REAR	0.00	\$122.80	0.00	\$0.00	Replace	Not Given X
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
58311471 30	SPARE TYRE PANEL , PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Not Given X
81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given X
52461470 10	PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given X
52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace ✓
52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace ✓
52599680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given X
52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given X
52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check X
52565479 00	FILLER, RR BUMPER , RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X
52566479 00	FILLER, RR BUMPER , LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X
52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given X
52462470 10	PAD, RR BUMPER, RH & LH , 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X
52462470 20	PAD, RR BUMPER, RH & LH , 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X
52462470 30	PAD, RR BUMPER, RH & LH , 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X
52161160 10	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given X
52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair R
Total			\$9,878.80		\$692.42		

1416.70
- 200
1133.12
+ 200.00
+ 400.00
1733.12
215 \$1750f

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace ✓
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace ✓
		66259470 10	COVER, REAR FLOOR UNDER CENTER	1.00	\$222.60	25.00	\$166.95	Replace	Replace ✓
Total					965.30		723.98		