

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19	-96071	98-R	
		Affiliated to Federation Internation	nale Des Experts En Au	utomok	pile	
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI20011439/Acf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	20/01/2022	
			Co	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SKV 9375M	Veh. Inspected		YM 7253B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10007663JM	Excess (\$)		0.00	
	Assign From	ABIGAIL CHOO	Assign Date		21/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	ISUZU NHR85E	c.c		2999	
	Engine No.	HIDDEN	Year of Reg.		2007	
	Chassis No.	JAANHR85E77100256	Colour		WHITE	
	Odometer	323901 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/75 R16C	YOKOHAMA		6 mm	
	L/H Front Tyre	195/75 R16C	YOKOHAMA		6 mm	
	R/H Rear Tyre	185 R14C	YOKOHAMA		6 mm	
	L/H Rear Tyre	185 R14C	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	17/10/2020	Inspection Date		21/10/2020	
	Survey held at TWINCAR AUTOMOTIVE PTE LTD					
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	a. Remarks					
	A)THE INSPECTION	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D)III / (COOKDAIN)	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: