

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LKK Adm

KHAISENG TRADING & FISH FA PTE LTD
181 NEO TIEW RD
SINGAPORE 719023

ESTIMATE

Repair Code : CLM15062

Date in : 20/10/2020

Vehicle Num. : YM7253B

Model : ISUZU NHR85EU3ES

Chassis/Eng# : JAANHR85E77100256/4JJ1527136

Contact : 92393819, 98646592

TP Budget Direct.
Celine.

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR END PANEL <i>Repair</i>	1	297.30	X 297.30
REAR RH SIDE TAILGATE <i>Repair</i>	1	1980.00	X 1,980.00
REAR RH TAILLAMP <i>Crushed</i>	1	169.00	✓ 169.00
REAR TAILGATE <i>Dented</i>	1	1349.00	✓ 1,349.00
REAR TAILGATE HINGES <i>New</i>	4	50.00	+ 200.00
REAR TAILGATE SIDE LOCK BRACKET RH <i>Bent</i>	1	55.00	✓ 55.00
REAR TAILGATE SIDE LOCK L/R <i>RH Disturbed</i>	2	112.50	112.50 225.00
REAR TAILGATE SIDE LOCK STRIKER L/R <i>RH Bent</i>	2	39.00	39. 78.00
Subtotal before discount			4,353.30
Percentage discount 15%			653.00
Sub-total 1			3,700.31
REAR REINFORCEMENT <i>New</i>	1	800.00	X 800.00
REAR TAILGATE '60KM' STICKER <i>New</i>	1	25.00	15 25.00
REAR TAILGATE HINGES PIN - SET <i>New</i>	4	35.00	X 140.00
TO REMOVE & REPAIR TRANSMISSION GEARBOX <i>New</i>	1	3000.00	X 3,000.00
Subtotal before discount			3,965.00
Percentage discount 0%			0.00
Sub-total 2			3,965.00
Parts-total			7,665.31

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KHAISENG TRADING & FISH FA PTE LTD
181 NEO TIEW RD
SINGAPORE 719023

Contact : 92393819, 98646592

ESTIMATE

Repair Code : CLM15062

Date in : 20/10/2020

Vehicle Num. : YM7253B

Model : ISUZU NHR85EU3ES

Chassis/Eng# : JAANHR85E77100256/4JJ1527136

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, transmission gearbox, transfer and changing parts.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 .80.00

280 .450.00

600 1,000.00

400 1,000.00

50 120.00

1360

Labour Total

2,650.00

Parts & Labour Total

10,315.31

*** This is a computer-generated document which requires no signature.***

page 2

total: 2840.82

4/5: 2'2k. ✓

04 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: