

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG20011440/KGS3Q2

Date:

10/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900117681

Claimant Vehicle No : SHD530X**Insured Vehicle No :**

SMN3704E

Date of Loss: 19/10/2020

Nature of Claim:

TP

Claim No:

6550932335SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD530X**

Make & Model: RENAULT LATITUDE, 2.0 L (A)

Engine No:

M9R8839C003240

Reg. Date: 24/11/2017 (Man. Year: 2016)

Chassis No:

VF1ABL15AUC283495

Colour: Metallic White/Red

Odometer:

336155 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Sailun 9 mm

Rear Left Side:

Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side:

Sailun 9 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,809.23	4,527.56	3,281.67	42.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	1,300.00	2,460.00	65.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,569.23	5,827.56	5,741.67	49.63
+ GST 7.00/7.00% (S\$)	809.85	407.93	401.92	49.63

Nett Amount (S\$)	12,379.08	6,235.49	6,143.59	49.63
+ Car Rental (5.0 x S\$81.13/day) (S\$)		405.65		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,648.59		

INSPECTION

Date of Assignment: 20/10/2020

Date Inspected: 20/10/2020

Estimated Period of Repair: 3.0 days

Inspected At:

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST 63
SINGAPORE 569111

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled/Mtg Cracked	747.20 FL	*747.20 FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
3	1		*BUMPER RETAINER FRT LH	Distorted	101.40 FL	*101.40 FL
4	1		*HEADLAMP LH	Cut	743.60 FL	*743.60 FL
5	1		*HEADLAMP PANEL FRT LH	Repair	128.30 FL	*- FL
6	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
7	1		*FENDER PANEL FRT LH	Bent	437.10 FL	*437.10 FL
8	1		*WHEELARCH FRT LH	Serviceable	191.40 FL	*- FL
9	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
10	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
11	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
12	1		*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
13	1		*DOOR WAIST SEAL OUTER FRT LH	Serviceable	92.20 FL	*- FL
14	1		*DOOR MIRROR LH	Serviceable	1,483.40 FL	*- FL
15	1		*BUMPER CLIP FRT	Necessary	90.00 FS	*66.00 FS
16	1		*BUMPER RETAINER CLIP FRT	Not Necessary	75.00 FS	*- FS
17	1		*WHEELARCH CLIP FRT	Not Necessary	75.00 FS	*- FS
18	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
19	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,632.48	5,014.96
- List Item Discount on L Items 10.00/10.00% (\$)	823.25	487.40
Total Parts (\$)	7,809.23	4,527.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	230.00	60.00
2	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	660.00
4	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,400.00	500.00
5	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			3,760.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >