

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 27/10/2020

MODEL: HYUNDAI I 40

VEH NO.: SHC 959Z

3P INSURANCE: NTUC

SURVEYOR: LKK

MVA: LOKE WY

Star (LKK) Ltd AL
97/10/20, 3 days
L/S. Rg AL Rg

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Front Bumper Cover	✓ OR		\$1,052.20 ✓
	Front Bumper Sponge	X NM		\$99.20
	Front Bumper Reinforcement	X NM		\$438.40
	Front Bumper Bracket Top RH	✓ OR		\$22.40 ✓
	Front Bumper Bracket (RH)	✓ OR		\$24.60 ✓
	Front Bumper Grille RH	✓ OR		\$93.60 ✓
	Headlamp (RH)	✓ OR		\$1,388.00 ✓
	Front Bumper Protector RH	X NM		\$25.40
	Front Bumper Retainer Mounting RH	X NM		\$9.20
	Headlamp Support Panel Assy	✓ OR		\$907.40 ✓
	Front Fender (RH)	✓ OR		\$663.00 ✓
	Front Fender Shield (RH)	✓ TN		\$174.90 ✓
	Wiper Container	X NM		\$61.90
	Front Bonnet	X R		\$2,265.90
SPARE PARTS SUB TOTAL				\$7,226.10
LESS 20%				\$1,445.22
DISCOUNTED SPARE PARTS TOTAL				\$5,780.88
NETT TOTAL				\$-
SPARE PARTS & NETT TOTAL				\$5,780.88
	Panel Beating			\$600.00
	Spray Painting			\$800.00
	Check Wiring			\$60.00
	Tuff kote			\$60.00
LABOUR TOTAL				\$1,520.00
ESTIMATE TOTAL				\$7,300.88

4326.10
-20%
3460.88

560
600
30
30

1220

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company