

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SLZ7893P

Accident Date : 20/10/20

Location : MCE TOWARDS CTE

TP China
Celine

Model: NISSAN NOTE
(18/5/2018)

3P: XD2412B (CHINA TAIPING)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Gear box <i>Damaged</i>	-	-	13,691.20
2	1pc	Gear box oil <i>New</i>	-	80 120.00	-
3	1pc	Gear box sealant (Grey) <i>new</i>	-	50 80.00	-
4	1pc	Gear box oil Pan clw Gasket <i>Dislud</i>	-	-	16000
5	1pc	Front cross member <i>Best</i>	-	-	720.20
Sub-Total:			0.00	200.00	1457140
			30%	0%	10%
After Less %:			0.00	200.00	1311426
Labour					
1		To remove front o/s & n/s under carriage to facilitage removal of cross member		400.00 <i>300</i>	
2		To remove and replace gear box		800.00 <i>380</i>	
3		To reset gear box valve module		450.00 <i>x</i>	
Sub-Total:				1,650.00	
Total:				1496426	
After Less 20%:				1197140	

3500
(SN)

Chan

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)

Nett: 880120

Less 10%: 79218

S.N: 3630

Labour: 680



bizSAFE
S T R

8778 1999
24 hr accident call

Mobil 1



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLZ7893P ESTIMATEPg1

Total: 510218

w/s: A.K.

05 days

(Subjected to approval)