

ASS. REC. BY:

REF:

GAZ

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s S Three

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 819k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 03/24 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJP 575014 Yr Regn: 03, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 1-Hundai Avanta c.c. 1591Colour: M. Blue A/C: Insured / Std / Nil / NASp. Reading: 237872 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMHOU41BR9U712872Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 195/85R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal. 3 mmR/Bal. 2 mmL/Bal. 3 mmL/Bal. 2 mmD.O.A. 20/10/20D.O.I. 22/10/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/104th Release 88755.00LUMP SUM \$8900, 9DAYS
(RED: 12,149.04;57%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Authorized
L1 Sing @
Mesung After Pain

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : TRC2849B

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

CONTACT : _____

NAME : HO CHU LAN

ADDRESS : _____

CHASSIS NO : _____

ENGINE NO : _____

LICENSE NO. SJP5750H TRANS. :
MAKE / MODEL : HYUNDAI AVANTE
OWNER'S INSURER : BUDGET ASIA
JOB-CODE : TP S/A : MICHELLE

ACCIDENT DATE : 20-Oct-20

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER	1.00	\$ 566.00	20.00	\$ 452.80	Y	✓
2 FRONT BUMPER SIDE RETAINER RH	1.00	\$ 27.00	20.00	\$ 21.60	Y	✓
3 FRONT BUMPER SIDE RETAINER LH	1.00	\$ 27.00	20.00	\$ 21.60	Y	X
4 FRONT HEADLAMP RH	1.00	\$ 489.50	20.00	\$ 391.60	Y	✓
5 FRONT BUMPER FOG LAMP RH	1.00	\$ 385.00	20.00	\$ 308.00	Y	X
6 FRONT WING MIRROR RH	1.00	\$ 358.00	20.00	\$ 286.40	Y	?
7 FRONT DOOR RH	1.00	\$ 1,070.00	20.00	\$ 856.00	Y	✓
8 FRONT DOOR FRAME RH	1.00	\$ 21.00	20.00	\$ 16.80	Y	✓
9 FRONT FENDER RH	1.00	\$ 389.00	20.00	\$ 311.20	Y	✓
10 FRONT DOOR OUTER MOULDING RH	1.00	\$ 48.00	20.00	\$ 38.40	Y	X
11 FRONT DOOR HINGE UPPER RH	1.00	\$ 188.00	20.00	\$ 150.40	Y	X
12 FRONT DOOR HINGE LOWER RH	1.00	\$ 188.00	20.00	\$ 150.40	Y	X
13 FRONT DOOR GLASS CHANNEL RH	1.00	\$ 111.00	20.00	\$ 88.80	Y	X
14 FRONT DOOR LOCK RH	1.00	\$ 238.00	20.00	\$ 190.40	Y	✓
15 FRONT DOOR HANDLE RH	1.00	\$ 46.00	20.00	\$ 36.80	Y	✓
16 FRONT DOOR INNER HANDLE RH	1.00	\$ 37.00	20.00	\$ 29.60	Y	?
17 FRONT DOOR RUBBER BEADING RH	1.00	\$ 118.00	20.00	\$ 94.40	Y	?
18 FRONT DOOR TRIM BOARD RH	1.00	\$ 586.00	20.00	\$ 468.80	Y	X
19 FRONT DOOR CHECK LINK RH	1.00	\$ 48.00	20.00	\$ 38.40	Y	X
20 FRONT DOOR TOP FRAME RUBBER BEADING RH	1.00	\$ 21.00	20.00	\$ 16.80	Y	?
21 FRONT DOOR GLASS REGULATOR RH	1.00	\$ 238.00	20.00	\$ 190.40	Y	X
22 FRONT DOOR GLASS MOTOR RH	1.00	\$ 210.00	20.00	\$ 168.00	Y	X
23 FRONT SHOCK ABSORBER RH	1.00	\$ 187.00	20.00	\$ 149.60	Y	?
24 FRONT SHOCK ABSORBER LH	1.00	\$ 187.00	20.00	\$ 149.60	Y	?
25 FRONT KNUCKLE ARM RH	1.00	\$ 352.00	20.00	\$ 281.60	Y	?
26 FRONT KNUCKLE ARM LH	1.00	\$ 352.00	20.00	\$ 281.60	Y	?
27 FRONT LOWER ARM RH	1.00	\$ 279.00	20.00	\$ 223.20	Y	?
28 FRONT LOWER ARM LH	1.00	\$ 279.00	20.00	\$ 223.20	Y	?
29 FRONT KNUCKLE ARM BEARING RH	1.00	\$ 111.00	20.00	\$ 88.80	Y	?
30 FRONT KNUCKLE ARM BEARING LH	1.00	\$ 111.00	20.00	\$ 88.80	Y	?
31 REAR BUMPER	1.00	\$ 442.00	20.00	\$ 353.60	Y	X

8	FRONT SPORT RIM LH	<i>Ne</i>	1.00	\$	680.00	0.00	\$	680.00	Y	<i>2501m</i>
9	FRONT TYRE RH		1.00	\$	280.00	0.00	\$	280.00	Y	<i>7</i>
10	FRONT TYRE LH		1.00	\$	280.00	0.00	\$	280.00	Y	<i>7</i>
11	REAR SPORT RIM RH	<i>Sn</i>	1.00	\$	680.00	0.00	\$	680.00	Y	<i>X</i>
12	REAR SPORT RIM LH	<i>Ne</i>	1.00	\$	680.00	0.00	\$	680.00	Y	<i>2501m</i>
13	REAR TYRE RH	<i>Sn</i>	1.00	\$	280.00	0.00	\$	280.00	Y	<i>X</i>
14	REAR TYRE LH	<i>•</i>	1.00	\$	280.00	0.00	\$	280.00	Y	<i>7</i>

TOTAL (PARTS) : \$ 4,280.00 \$ 4,280.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA		1.00	\$	1,800.00	0.00	\$	1,800.00	Y	<i>800</i>
2	SPRAY PAINTING ON ACCIDENT AREA		1.00	\$	1,600.00	0.00	\$	1,600.00	Y	<i>1000</i>
3	RESPRAY TUFF KOTE ON ACCIDENT AREA		1.00	\$	180.00	0.00	\$	180.00	Y	<i>90</i>
4	CONDUCT FULL WHEEL ALIGNMENT		1.00	\$	120.00	0.00	\$	120.00	Y	<i>80</i>
5	CHECK WIRING SYSTEM		1.00	\$	180.00	0.00	\$	180.00	Y	<i>40</i>
6	R&R FRONT UNDERCARRIAGE SYSTEM		1.00	\$	380.00	0.00	\$	380.00	Y	<i>7</i>
7	R&R REAR UNDERCARRIAGE SYSTEM		1.00	\$	380.00	0.00	\$	380.00	Y	<i>7</i>
8	R&R FRONT DOOR COMPARTMENT RH		1.00	\$	120.00	0.00	\$	120.00	Y	<i>60</i>
9	R&R REAR DOOR COMPARTMENT RH		1.00	\$	120.00	0.00	\$	120.00	Y	<i>60</i>

TOTAL (LABOUR) :

\$ 4,880.00 \$ 4,880.00

TOTAL PARTS & LABOUR

\$ 22,176.80 \$ 19,573.44

EXCESS : : \$ \$

NO. OF DAY : *08*

RE-SURVEY : ~~BEFORE~~ / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$ \$

DATE OF SURVEY : *22/10/20*

SURVEY BY : *Menach*

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

SKETCH PLAN

A - SJPS750H
 B - TRC2849B
 (Prime Mover) XD2097C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While driving straight on the extreme left lane along Gul Way, vehicle B suddenly drive very close to my lane. I slowed down and honned at him but vehicle B continue to drive into my lane hit and grazed the right portion of my vehicle. due to the impact my vehicle was being pushed to hit the kerb on the left both right and left portion of my vehicle was damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

