



# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

NTUC/FC(SHA8448P)

DOA: 14/10/2020@0910

MS FIRST CAPITAL INSURANCE PTE LTD

ATTN: THE MOTOR CLAIMS DEPT

## THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SLH 5914 X - HONDA VEZEL HYBRIDE 1.5X AUTO

CHASSIS NO: RU31218358 (11/2016)

- |       |                                          |
|-------|------------------------------------------|
| 1 pc  | Front headlamp LH                        |
| 1 pc  | Front bumper                             |
| 1 pc  | Front bumper retainer LH                 |
| 1 pc  | Front bumper foglight cover LH           |
| 1 pc  | Front bumper lower spoiler               |
| 1 pc  | Front fender LH                          |
| 1 pc  | Front fender emblem 'HYBRID' emblem      |
| 1 pc  | Front fender inner shield LH             |
| 6 pcs | Front fender inner shield clips @ \$3.90 |
| 1 pc  | Front fender wheel arch protector LH     |
| 1 pc  | Wiper garnish side rubber LH             |
| 1 pc  | Wiper garnish seal                       |

LESS 20%

Check wiring function

Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front wheel house LH, front chassis LH, front support panel inclusive replacing the above.

Putty and respray front bonnet, front bumper, front fender LH, front chassis LH, front support panel, front wheel house and front door LH.

ADD 7% GST

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

19-10-20

Tanpin 9749549  
wp' 27/10/2020 3pm

Lumpsum  
Resurvey after repair  
3-4 days  
tanpin@lumpsum.com

|             |      |
|-------------|------|
| \$ 1,735.50 | car  |
| \$ 864.20   | de   |
| \$ 19.90    | car  |
| \$ 34.60    | wt   |
| \$ 360.20   | de   |
| \$ 450.80   | bt   |
| \$ 69.50    | wt   |
| \$ 125.80   | wt   |
| \$ 23.40    | wt   |
| \$ 166.20   | wt   |
| \$ 39.00    | x    |
| \$ 135.60   | <    |
| <hr/>       |      |
| \$ 4,024.70 |      |
| \$ 804.94   |      |
| <hr/>       |      |
| \$ 3,219.76 |      |
| <hr/>       |      |
| \$ 40.00    | 30.  |
| <hr/>       |      |
| \$ 800.00   | 400. |

|             |     |
|-------------|-----|
| \$ 800.00   | 600 |
| \$ 4,859.76 |     |
| \$ 340.18   |     |
| <hr/>       |     |
| \$ 5,199.94 |     |

CHARN'S CUSTOMCRAFT