

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CC4/ASM20011457/UB93**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBB3014

at Workshop m/s

Asia Motor Sport.

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

413k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

564D

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBB3014

Yr Regn:

6108

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

M.F center FB70 c.c 2977

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

245328

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FB70 BBA10489

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

OHTS4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

17/10/20

D.O.I.

22/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

, o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

we 31-8-2022 LTA 665716/11/20 confirmed w/s 2500 m.h AH long

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

VEHICLE NO. GBB301Y

MITSUBISHI Carter

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Rear Tailgate panel		2150.00	X
1	RHS panel	2450	2850.00	—
1	Rear Tailgate hinges	100/	250.00	X
1	Rear taillamps RHS	11	598.00	X
1	Rear taillamps bracket RHS	11C	122.00	X
1	RHS corner bracket	181.00	320.00	—
1	RHS corner bracket stopper		60.00	—
1	RHS mud flap guard		125.00	—
1	Rear exhaust pipe assy		2310.00	X
			8785.00	
		less	25%	25%
			2196.25	
			6588.75	
	SPECIAL NETT ITEMS			
1	RHS panel company sticker		450.00	250
1	13 Pax sticker		20.00	10
1	70km/h sticker		20.00	10
			7078.75	

not Allowed
 2/5 \$ 2500
 4 days.

P-2816
 253
 P-2412
 S.V-270
 L-760
 3142
 20%
 2513.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO. GBB301Y MITSUBISHI Carter

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts to commence repairs; replace damaged parts	1000.00	- 300
2	To supply paint materials, expandable items & putty, respray paint on repaired areas	800.00	- 430
3	To remove and refix wiring	120.00	- 11X
4	To remove and replace exhaust pipe assy	250.00	- 11X
5	To perform anti rust treatment on affected areas	250.00	30
	Labour Total :	2420.00	
	TOTAL (PARTS & LABOUR):	9498.75	