

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBE9189E

Not Authorized
C/Sy B
Resurvey After Paint
6 days

No.	Qty	List Items		
1	1	Rear tailgate	R	\$ 1,337.00 ✓
2	1	Rear deck end panel	\$ R	848.00 ✓
3	1	LH taillamp bracket	\$ R	183.40 ✓
4	2	Taillamp	\$ R	528.40
5	1	Rear number plate bracket	\$ R	145.10 X
6	1	Rear number plate lamp	\$ R	69.00 X
7	1	Rear lower spare tyre carrier chain	\$ R	254.00 X
8	1	Rear LH side gate	\$ R	1,337.00 ✓
9	1	Rear LH side gate lower lock catch	\$ R	54.10 ✓
10	1	Rear LH side gate lower stopper bracket	\$ R	123.10 ✓
11	1 set	Rear side lower rubber stopper	\$ R	69.10 X
			\$	4,948.20
			Less 25%	\$ 1,237.05
			Total :	\$ 3,711.15

		Special Nett Items		
12	1	Rear number plate	\$ R	45.00 X
13	1	Reverse sensors	\$ R	350.00 ?
14	1	Rear tailgate inner metal protection panel	\$ R	600.00 ✓
15	1 set	Rear tailgate/rear LH side gate sticker set	\$ R	650.00 500
16	1	Rear tailgate "13pax" sticker	\$ R	15.00 125
17	1	Rear tailgate "70km/h" sticker	\$ R	15.00 125
			Total :	\$ 1,675.00

		Labour		
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,100.00 800
2		To putty and spray Spray Paintings charges.	\$	1,200.00 800
3		To check wirings & lightings.	\$	40.00 20
4		To remove, refit reverse sensors.	\$	60.00 50
5		To supply and apply anti rust treatment	\$	80.00 60
			Total :	\$ 2,480.00

Total Parts and Labour : \$ 7,866.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: