

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBE9189E

Not Authorized
C1 Sup & 4700h
Returning After Pain
6 days

No.	Qty	List Items			
1	1	Rear tailgate	1265	R	\$ 1,337.00 —
2	1	Rear deck end panel		R	\$ 848.00 —
3	1	LH taillamp bracket	175	R	\$ 183.40 —
4	2	Taillamp	015u x	1112M	\$ 528.40 LT
5	1	Rear number plate bracket		R	\$ 145.10 X
6	1	Rear number plate lamp		R	\$ 69.00 X
7	1	Rear lower spare tyre carrier chain		R	\$ 254.00 X
8	1	Rear LH side gate		R	\$ 1,337.00 —
9	1	Rear LH side gate lower lock catch		R	\$ 54.10 —
10	1	Rear LH side lower rubber stopper bracket		R	\$ 123.10 —
11	1 set	Rear side lower rubber stopper		R	\$ 69.10 X
					\$ 4,948.20
			Less 25%		\$ 1,237.05
			Total :		\$ 3,711.15

Special Nett Items

12	1	Rear number plate		\$ 45.00 X
13	1	Reverse sensors	short	\$ 350.00 2005N
14	1	Rear tailgate inner metal protection panel		\$ 600.00 — 4205N
15	1 set	Rear tailgate/rear LH side gate sticker set		\$ 650.00 500L
16	1	Rear tailgate "13pax" sticker		\$ 15.00 125N
17	1	Rear tailgate "70km/h" sticker		\$ 15.00 125N
			Total :	\$ 1,675.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,100.00 800L
2	To putty and spray Spray Paintings charges.	\$ 1,200.00 800L
3	To check wirings & lightings.	\$ 40.00 20L
4	To remove, refit reverse sensors.	\$ 60.00 50L
5	To supply and apply anti rust treatment	\$ 80.00 60L
		Total : \$ 2,480.00

Total Parts and Labour : \$ 7,866.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: