



PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 22/10/2020
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D20MTHCVE001720 Accident Date : 16/10/2020
Vehicle No : GBK-4395-C Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>Nett Item</u>			
1	HEADLAMP LH	353.00	X nn
1	FRT BUMPER	571.90	Rx
10	FRT BUMPER CLIPS	50.00	XX nn
1	FRT BUMPER SIDE BRACKET LH	164.50	? X nn
1	"A" PILLAR LH	RESTORE Xnn	
1	SIDE MIRROR LH		
1	FRT DOOR LH	478.80	ann
1	FRT DOOR HINGE LH (UPPER)	1,071.80	bt
1	FRT DOOR HINGE LH (LOWER)	68.50	Kv
		68.50	fx

Date : 22/10/2020

To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE001720

Accident Date : 16/10/2020

Vehicle No : GBK-4395-C

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRT DOOR CHECKER LH	48.90	X nn
1	FRT DOOR GLASS OUTER MLDG LH	157.50	X nn
1	FRT DOOR GLASS REGULATOR LH	155.30	X nn
1	FRT DOOR GLASS REGULATOR MOTOR LH	568.40	X nn
1	FRT DOOR LOCK LH	172.80	X nn
1	FRT DOOR TRIMBOARD LH	504.60	X nn
1	SIDE STEP GARNISH LH	47.90	X nn
1	CENTRE PILLAR LH	1,386.50	R
1	SLIDING DOOR LH	1,325.40	bj
1	REAR FENDER LH		
	RESTORE	X R	

Date : 22/10/2020

To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE001720

Accident Date : 16/10/2020

Vehicle No : GBK-4395-C

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAIL LAMP LH	224.80	✓ Cra
3	TAIL LAMP CLIPS	30.00	?X nn
1	REAR BUMPER		
	RESTORE		
1	FRT SHOCK ABSORBER LH	140.20	X
1	FRT UPPER ARM LH	377.50	X
1	FRT KNUCKLE ARM LH	351.50	? } nn
1	FRT WHEEL BEARING LH	231.00	? }
1	FRT LOWER ARM LH	228.70	X
1	FRT STEEL RIM LH	361.70	X
1	FRT STEEL RIM CAP LH	181.30	mis ✓

Type text here

Date : 22/10/2020
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D20MTHCVE001720 Accident Date : 16/10/2020
Vehicle No : GBK-4395-C Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (V
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	9321.00	
	Discount 10% On Parts	(932.10)	
	<u>Special Nett Item</u>		
1	FRT DOOR ADV STICKER LH	150.00	net / 100
1	ROC STICKER (LH)	10.00	net /
1	SLIDING DOOR ADV STICKER LH	250.00	net / 200
1	REAR FENDER ADV STICKER LH	450.00	net / 400
1	REAR BUMPER ADV STICKER	450.00	net / 400
1	TOWING FEE	60.00	net /

Date : 22/10/2020
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D20MTHCVE001720 Accident Date : 16/10/2020
Vehicle No : GBK-4395-C Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Sub Total		1370.00	
<u>Labour & Misc</u>			
	LABOUR TO FACILIATE REPAIR	1,200.00	800.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	30.
	TO SPRAY PAINT ON AFFECTED AREAS	1,600.00	1000.
	SPRAY RUST PROOF ON AFFECTED AREA	60.00	40.
	TO REMOVE & INSTALL ALL L/H/F DOOR COMPONENTS TO FACILIATE REPAIR	150.00	60
	TO REMOVE & INSTALL ALL L/H/R DOOR COMPONENTS TO FACILIATE REPAIR	150.00	60.

Date : 22/10/2020

To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE001720

Accident Date : 16/10/2020

Vehicle No : GBK-4395-C

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO REMOVE & REFIT ALL NECESSARY TRIM BOARDS, GARNISH, CARPET, FLOOR MATS & SEAT	150.00	60
	TO REMOVE & RENEW ALL L/H/F UNDERCARRIAGE PARTS TO ASSIST REPAIR	250.00	150? plus nn
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	100.00	80
	Sub Total	3695.00	
	<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	13,453.90	
Remarks:	Acknowledged by Repairer Signature: Date:		
	SUB TOTAL		
	GST 7.0 %	941.77	
	TOTAL	14,395.67	

Surveyor's name:

Tan Min 97495749

7 days

Principal's name:

ETHOZ Group Ltd

-wp-

Survey Date & Time:

22/10/20 @ 4.15pm

Tan Min @ LKK Auto

*To check sticker price
p/p Resurvey before paint

PAGE: 6

ETHOZ GROUP LTD

30 Bukit Batok Crescent, Singapore 658075 | Tel 6319 8000 | Fax 6654 7543 | www.ethozgroup.com

Company Registration No. 198149531M