FASTECH AUTO PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-48, AUTO BAY SINGAPORE 417883

Well HS140 TONG

Not Authorid 23/10/20 1/5 \$ 4200 tolys thephe Hang

VEHICLE No: GBD 8166H

1PC 1PC 2PCS 1PC	FRONT DOOR O/S FRONT DOOR SIGNAL LAMP O/S /3520 FRONT DOOR HINGES @\$105.00 FRONT DOOR INNER RUBBER O/S FRONT DOOR INNER LOCK O/S FRONT DOOR INNER TRIM BOARD O/S FRONT STEP PANEL O/S FRONT STEP PANEL O/S FRONT BUMPER FRONT BUMPER FOG LAMP O/S 385-20 FRONT BUMPER FOG LAMP COVER O/S /0510 FRONT BUMPER BRACKET O/S /7520 FRONT GRILLE FRONT GRILLE FRONT GRILLE LOGO CORNER PANEL O/S FRONT DOOR PILLAR O/S FRONT DOOR 'ROC' STICKER O/S HEADLAMP CLIP O/S TO CHECK WIRING	Sady
	TO SPRAY RUST PROOFING TO TRANSFER FRONT DOOR MECHANISM TO DISMANTLE & REFIX FRONT WINDSCREEN TO DISMANTLE & REFIX FRONT DASHBOARD LABOUR FOR PANEL BEATING & REPLACED PARTS TO PUTTY & SPRAY PAINTING	\$50.00 20 \$60.00 50 \$80.00 60 \$100.00 \$280.00 \$280.00 \$1,000.00 \$1,200.00 \$700 \$1,200.00 700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2818.60 764.60 764.60 764.60