

Blk 1009 Bukit Merah Lane 3 #01-96 S(159723)
HP: 9737 2883 / Off: 9232 9816 E: daniel9633@hotmail.co.uk

QUOTATION

NO.: QZD0118

VEHICLE NO.: SCP5555M

VEHICLE MODEL: Honda Vezel

DATE OF ACCIDENT: 17/10/2020

YOUR REF: SHC1642E

DATE: 20/10/2020

M/S: India International Insurance Pte Ltd
64 Cecil Street #04/#05-02
IOB Building
Singapore 049711
Tel: 63476100
Email address: motorclaim@iii.com.sg

Dear Sir,

Replacement of parts

1. Front right door	\$950.00
2. Rear right door	\$930.60
	\$1880.60
	Less 10% \$188.06
	Subtotal: \$1692.54
Labour charges	
1. To remove front right door & transfer door mechanism to new & realign.	\$300.00
2. To remove rear right door & transfer door mechanism to new & realign.	\$300.00
3. To respray front right door & rear right door.	\$600.00
	Grand total: \$2892.54