

杰
艺

汽車修理服務中心
ZENITH DANIEL AUTO SERVICES

Blk 1009 Bukit Merah Lane 3 #01-96 S(159723)
HP: 9737 2883 / Off: 9232 9816 E: daniel9633@hotmail.co.uk

QUOTATION
NO.: QZD0118
VEHICLE NO.: SCP5555M
VEHICLE MODEL: Honda Vezel
DATE OF ACCIDENT: 17/10/2020
YOUR REF: SHC1642E
DATE: 20/10/2020

M/S: India International Insurance Pte Ltd
64 Cecil Street #04/#05-02
IOB Building
Singapore 049711
Tel: 63476100
Email address: motorclaim@iii.com.sg

Dear Sir,

Replacement of parts

1. Front right door *bt*
2. Rear right door *bt*

1564.48
55.00
900.00
2459.48
20%
1967.58

4/8-1,950
4 days

1880.60 \$950.00
20% \$930.60
1504.48 Less 10% \$1880.60
\$188.06

3. Rear right door w/strip *at*

Subtotal: \$1692.54

55

\$55.00 N.

Labour charges

1. To remove front right door & transfer door mechanism to new & realign.
2. To remove rear right door & transfer door mechanism to new & realign.
3. To respray front right door & rear right door.

900 { 200 ~~\$300.00~~
200 ~~\$300.00~~
500 ~~\$600.00~~

Grand total: \$2892.54

RAME

Hp 90010068

4 days

4/8

23/10/2020 @ 1110

Res after repair

Daniel Tan 9737 2883

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: