



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 36983

not Authorised
23/10/20
3 days.

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

DATE : 21/10/2020
CLAIM NO. : 11633
POLICY NO. : MC/00833658
FROM : HASRIANAH

ATTN: MS FIRST CAPITAL INSURANCE LTD

VEHICLE NO. : FBN1567C
MAKE/MODEL : YAM / NMAX155 ABS

p/p 8/207

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER P/N: 55166 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$12.00	24.00
2	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
3	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00	53.00
4	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00	53.00
5	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$222.00	222.00
6	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
7	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
8	COVER CLUTCH OUTER DAMPER 2 P/N: 58172 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00
9	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00

*36983 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
10	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
11	COVER SIDE REAR LH (WHITE) P/N: 58170 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
12	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	33.00
13	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	11.00
14	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$189.00	189.00
15	LEVER BRAKE RH P/N: 58185 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
16	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
17	PANEL 1 (GREY) LH P/N: 60905 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00
18	Spray Lacquer on cover side LH	Spray	1.00	\$91.00	91.00
19	Spray Lacquer on cover side RH	Spray	1.00	\$91.00	91.00
20	Spray Lacquer on front cowl LH	Spray	1.00	\$91.00	91.00
21	Spray Lacquer on lower side cover LH	Spray	1.00	\$35.00	35.00
22	Spray Lacquer on lower side cover RH	Spray	1.00	\$35.00	35.00
23	Spray paint on cover side LH	Spray	1.00	\$91.00	91.00
24	Spray paint on cover side RH	Spray	1.00	\$91.00	91.00
25	Spray paint on lower side cover LH	Spray	1.00	\$35.00	35.00
26	Spray paint on lower side cover RH	Spray	1.00	\$35.00	35.00
27	STAND MAIN P/N: 58138 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	66.00

*36983 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
28	STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH REPLACE P/N: 61181 - (REPORTED BY MECHANIC)	REPLACE	4	1.00 \$44.00	mer 44.00 ✓
29	STICKER (CISCO) COVER CENTRE LH P/N: 58614 - (REPORTED BY MECHANIC)	REPLACE	1	1.00 \$37.00	mer 37.00 ✓
30	STICKER (CISCO) COVER CENTRE RH P/N: 58615 - (REPORTED BY MECHANIC)	REPLACE	1	1.00 \$37.00	mer 37.00 ✓
31	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1	1.00 \$37.00	mer 37.00 ✓
32	STICKER (CISCO) LINING COVER REAR LH P/N: 61573 - (REPORTED BY MECHANIC)	REPLACE	1	1.00 \$15.00	mer 15.00 ✓
33	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1	1.00 \$56.00	35 56.00

SUB TOTAL

\$1,686.00

GST @ 7 %

\$118.02

GRAND TOTAL (SGD)

\$1,804.02

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

P-580
 100
 P-522
 L-180
 S.N-170
 SPY-300
 100-35
 1207.

*36983 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363
ISO 9001:2015



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MS FIRST CAPITAL INSURANCE LTD

NO. : 36983

- Rev. 1

DATE : 21/10/2020
CLAIM NO. : 11633
POLICY NO. : MC/00833658

FROM : HASRIANAH

VEHICLE NO. : FBN1567C
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER P/N: 55166 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
2	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00 Disc %: 10.00	30.60
3	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00 Disc %: 10.00	47.70
4	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00 Disc %: 10.00	47.70
5	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$222.00 Disc %: 10.00	199.80
6	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
7	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
8	COVER CLUTCH OUTER DAMPER 2 P/N: 58172 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00 Disc %: 10.00	6.30
9	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00 Disc %: 10.00	6.30

*36983 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-140363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
10	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
11	COVER SIDE REAR LH (WHITE) P/N: 58170 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00 Disc %: 10.00	33.30
12	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00 Disc %: 10.00	29.70
13	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00 Disc %: 10.00	9.90
14	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$180.00	180.00
15	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00 Disc %: 10.00	33.30
16	PANEL 1 (GREY) LH P/N: 60905 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00 Disc %: 10.00	19.80
17	Spray Paint & Lacquer - COVER SIDE LH&RH, LOWER SIDE COVER LH & RH, FRONT COWLING	Spray	1.00	\$300.00	300.00
18	STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH P/N: 61181 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$44.00	44.00
19	STICKER (CISCO) COVER CENTRE LH P/N: 58614 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
20	STICKER (CISCO) COVER CENTRE RH P/N: 58615 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
21	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
22	STICKER (CISCO) LINING COVER REAR LH P/N: 61573 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	15.00
23	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$35.00	35.00

SUB TOTAL

\$1,207.00

GST @ 7 %

\$84.49

GRAND TOTAL (SGD)

\$1,291.49

*36983 *

bizSAFE₃

Address: No. 6, Detu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-14083
ISO 1001 2015