

QUOTATION

Customer :

NO. : **36983**

MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

DATE : 21/10/2020
 CLAIM NO. : 11633
 POLICY NO. : MC/00833658

ATTN: MS FIRST CAPITAL INSURANCE LTD

FROM : HASRIANAH

VEHICLE NO. : FBN1567C
 MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER P/N: 55166 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$12.00	24.00
2	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
3	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00	53.00
4	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00	53.00
5	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$222.00	222.00
6	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
7	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
8	COVER CLUTCH OUTER DAMPER 2 P/N: 58172 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00
9	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00

*36983 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
10	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
11	COVER SIDE REAR LH (WHITE) P/N: 58170 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
12	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	33.00
13	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	11.00
14	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$189.00	189.00
15	LEVER BRAKE RH P/N: 58185 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
16	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
17	PANEL 1 (GREY) LH P/N: 60905 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00
18	Spray Lacquer on cover side LH	Spray	1.00	\$91.00	91.00
19	Spray Lacquer on cover side RH	Spray	1.00	\$91.00	91.00
20	Spray Lacquer on front cowling LH	Spray	1.00	\$91.00	91.00
21	Spray Lacquer on lower side cover LH	Spray	1.00	\$35.00	35.00
22	Spray Lacquer on lower side cover RH	Spray	1.00	\$35.00	35.00
23	Spray paint on cover side LH	Spray	1.00	\$91.00	91.00
24	Spray paint on cover side RH	Spray	1.00	\$91.00	91.00
25	Spray paint on lower side cover LH	Spray	1.00	\$35.00	35.00
26	Spray paint on lower side cover RH	Spray	1.00	\$35.00	35.00
27	STAND MAIN P/N: 58138 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	66.00

*36983 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
28	STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH P/N: 61181 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$44.00	44.00
29	STICKER (CISCO) COVER CENTRE LH P/N: 58614 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
30	STICKER (CISCO) COVER CENTRE RH P/N: 58615 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
31	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
32	STICKER (CISCO) LINING COVER REAR LH P/N: 61573 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	15.00
33	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00	56.00

SUB TOTAL	\$1,686.00
GST @ 7 %	\$118.02
GRAND TOTAL (SGD)	\$1,804.02

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

***36983 ***

