



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103706

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 26/05/2021
Reference CC3/CTI20011474/Qrs3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 4470P
Insured Veh. SKG 8883Z
Claim No. SNM20D203959
Policy No. DMPCSNW00033952000
Accident Date 20/10/2020
Inspection Date 20/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20011474/Qrs3q2 Date: 26/05/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKG 8883Z	Veh. Inspected	SHC 4470P	
Policy No.	DMPCSNW00033952000	Coverage (\$)	0.00	
Claim No.	SNM20D203959	Excess (\$)	0.00	
Assign From		Assign Date	20/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU603573062	Colour	MAROON	
Odometer	286966 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	6 mm	
L/H Front Tyre	195/65 R15	SAILUN	6 mm	
R/H Rear Tyre	195/65 R15	SAILUN	6 mm	
L/H Rear Tyre	195/65 R15	SAILUN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/10/2020	Inspection Date	20/10/2020	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4470P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.73
1	NAME PLATE (PRIUS) LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	52.30	39.23
1	NAME PLATE (HYBRID) LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	52.30	39.23
1	TAIL GATE WEATHERSTRIP BACK DOOR (DISC 25%)	BROKEN	360.70	270.53
3	PAD RR BUMPER CTR @\$2.20 (DISC 25%)	NECESSARY	6.60	4.95
1	COVER GUARD RR BUMPER LOWER (DISC 25%)	SCRATCHED	14.80	11.10
1	GUARD ,RR BUMPER LOWER (DISC 25%)	SCRATCHED	558.30	418.73
2	PAD ,RR BUMPER RH & LH 3 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD ,RR BUMPER RH & LH 2 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD ,RR BUMPER RH & LH 1 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
10	CLIPS PIECE FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	COVER ,RR BUMPER ASSY (DISC 25%)	CRUMPLED	423.90	317.93
1	FILLER RR BUMPER LH (DISC 25%)	CUT	119.90	89.93
1	FILLER RR BUMPER RH (DISC 25%)	CUT	119.90	89.93
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	LENS & BODY ASSY ,RR BUMPER RH (DISC 10%)	CRACKED	486.80	438.12
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
1	COVER REAR COMBINATION LAMP LH	SERVICEABLE	54.00	-
1	LENS & BODY ,REAR COMBINATION LAMP LH	SERVICEABLE	438.10	-
1	COVER,REAR COMBINATION LAMP RH	SERVICEABLE	54.00	-
1	LENS & BODY ,REAR COMBINATION LAMP RH	SERVICEABLE	438.10	-
1	PANEL ASSY DECK TRIM SIDE ,RH	SERVICEABLE	344.70	-
1	PANEL ASSY DECK TRIM SIDE ,LH	SERVICEABLE	344.70	-
1	BOX ,DECK FLOOR ,RH	SERVICEABLE	304.00	-
1	BOX ,DECK FLOOR ,LH	SERVICEABLE	303.40	-
1	BOARD REAR FLOOR NO.1	SERVICEABLE	502.20	-

Report Ref No. CC3/CTI20011474/Qrs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE PANEL PAN REAR FLOOR	SERVICEABLE	564.80	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	END PANEL COVER DECK TRIM REAR	SERVICEABLE	122.80	-
1	END PANEL COVER DECK TRIM SERVICE HOLE	SERVICEABLE	47.00	-
1	LAMP SET ,STOP CENTER	SERVICEABLE	186.50	-
1	SPOILER SUB-ASSY ,REAR	SERVICEABLE	1,322.10	-
1	ANTENNA ,ELECTRICAL KEY	SERVICEABLE	60.30	-
1	SEALANT W/SCREEN	SERVICEABLE	37.00	-
1	TAIL GATE MOULDING LOWER GLASS ,BACK	SERVICEABLE	19.70	-
1	TAIL GATE MOULDING LOWER GLASS ,BACK	SERVICEABLE	29.90	-
1	TAIL GATE MOULDING LOWER GLASS,BAKC	SERVICEABLE	29.90	-
1	TAIL GATE DAM ,BACK DOOR GLASS UPPER	SERVICEABLE	27.90	-
1	TAIL GATE MOULDONG GLASS ,BACK DOOR	SERVICEABLE	29.70	-
1	TAIL GATE DAM ,BACK DOOR GLASS UPPER	SERVICEABLE	27.90	-
1	TAIL GATE STRIKER ASSY ,BACK DOOR	SERVICEABLE	24.90	-
1	TAIL GATE LOCK COVER ,BACK DOOR	SERVICEABLE	25.30	-
1	TAIL GATE LOCK ASSY ,BACK DOOR	SERVICEABLE	452.10	-
1	TAIL GATE PANEL SUB-ASSY ,BACK DOOR	SERVICEABLE	929.60	-
1	CLIP ,FLOOR UNDER COVER ,NO.2	SERVICEABLE	3.20	-
1	CLIP ,FLOOR UNDER COVER ,NO.1	SERVICEABLE	2.60	-
1	COVER ,REAR FLOOR UNDER CENTER	SERVICEABLE	222.60	-
1	COVER ,REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
1	COVER ,REAR FLOOR UNDER, LH	SERVICEABLE	234.30	-
1	WIRE LUGGAGE ROOM	SERVICEABLE	143.50	-
1	LENS & BODY ASSY ,RR BUMPER ,LH	SERVICEABLE	486.80	-
1	LENS & BODY ASSY ,RR BUMPER ,RH	SERVICEABLE	486.80	-
1	SEAL ,RR BUMPER ,RH	SERVICEABLE	85.20	-
1	SEAL ,RR BUMPER ,LH	SERVICEABLE	85.20	-
1	RETAINER ,RR BUMPER ,RH	SERVICEABLE	112.70	-
1	RETAINER ,RR BUMPER ,LH	SERVICEABLE	111.50	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	FILLER ,RR BUMPER ,RH	SERVICEABLE	119.90	-
1	FILLER ,RR BUMPER ,LH	SERVICEABLE	119.90	-

Report Ref No. CC3/CTI20011474/Qrs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SEAL ,RR BUMPER ARM RH & LH	SERVICEABLE	11.00	-
1	END PANEL SUBASSY ,BODY LOWER BACK	TO REPAIR SEE LABOUR	629.80	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	TO REPAIR SEE LABOUR	891.20	-
			13,919.90	2,351.26
	LABOUR			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF END PANEL SUBASSY ,BODY LOWER BACK AND TAIL GATE BACK DOOR OUTSIDE GARNISH SUB. SPRAY PAINT.		1,014.00	400.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		2,016.00	400.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		80.00	20.00
	TO TRANSFER REAR TAILGATE MECHANISM .	NOT NECESSARY	100.00	30.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM .		120.00	-
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR .	NOT NECESSARY	120.00	30.00
	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE .	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX REAR WINDSCREEN .	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	240.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	250.00	-
	TO WASH AND VACUUM .	NOT NECESSARY	100.00	-
			60.00	-
			4,340.00	880.00
GRAND TOTAL			18,259.90	3,231.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CC3/CTI20011474/Qrs3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 4470P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 4470P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

