



## Case Details

Case Reference Number :  
TAX/10/20/2037

Type of Repair : Accident Repair

Vehicle Registration Number :  
SHC4470P

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-12938-ID

Assigned By : Taxi Claims Manager  
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 19/10/2020 11 42 PM

Vehicle Age(In Months) : 36

## Documents / Photographs

View Documents / Photographs

Total Documents : 0

## Estimation Details

### Spare Part's Cost Detail

| BOM Type        | Costing Type | Portion | Material Number | Part Name                    | Qty | SMRT Recommendation     |                |        |                 | Repair/ Replace | Surveyor Approval |                          |                | Remarks |
|-----------------|--------------|---------|-----------------|------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
|                 |              |         |                 |                              |     | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) |                 | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |         |
| One Time Key In | Main         |         |                 | COVER, RR BUMPER ASSY        | 1   | 423.90                  | 423.90         | 25.00  | 317.92          | Replace         | 1                 | 317.92                   | Replace        | ✓ /CRU  |
| One Time Key In | Main         |         |                 | CLIPS PIECE, FRT & RR BUMPER | 10  | 1.50                    | 15.00          | 25.00  | 11.25           | Replace         | 10                | 11.25                    | Replace        | ✓ /Nec  |
| One Time Key In | Main         |         |                 | PAD, RR BUMPER, RH & LH , 1  | 2   | 3.80                    | 7.60           | 25.00  | 5.70            | Replace         | 2                 | 5.70                     | Replace        | ✓ /Nec  |
| One Time Key In | Main         |         |                 | PAD, RR BUMPER, RH & LH , 2  | 2   | 3.80                    | 7.60           | 25.00  | 5.70            | Replace         | 2                 | 5.70                     | Replace        | ✓ /Nec  |
| One Time Key In | Main         |         |                 | PAD, RR BUMPER, RH & LH , 3  | 2   | 3.80                    | 7.60           | 25.00  | 5.70            | Replace         | 2                 | 5.70                     | Replace        | ✓ /Nec  |
| One Time Key In | Main         |         |                 | SEAL, RR BUMPER ARM, RH & LH | 2   | 11.00                   | 22.00          | 25.00  | 16.50           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In | Main         |         |                 | FILLER, RR BUMPER , LH       | 1   | 119.90                  | 119.90         | 25.00  | 89.93           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In | Main         |         |                 | FILLER, RR BUMPER , RH       | 1   | 119.90                  | 119.90         | 25.00  | 89.93           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In | Main         |         |                 | REAR BUMPER REINFORCEMENT    | 1   | 318.80                  | 318.80         | 25.00  | 239.10          | Replace         | 0                 | 0                        | Check          | ✓ X SUC |

Total Spare Part Cost 10,281.91

Surveyor Total 1,494.12

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,225.53

Final Sur Total 1,195.30

| SMRT Recommendation |              |         |                 |                                 |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |          |
|---------------------|--------------|---------|-----------------|---------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|----------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                       | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks  |
| One Time Key In     | Main         |         |                 | SENSOR REVERSE                  | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace         | 1                 | 180.00                   | Replace        | ✓ /short |
| One Time Key In     | Main         |         |                 | PIXEL STICKER                   | 2   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace         | 2                 | 120.00                   | Replace        | ✓ /Nec   |
| One Time Key In     | Main         |         |                 | RETAINER, RR BUMPER, LH         | 1   | 111.50                  | 111.50         | 25.00  | 83.63           | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |
| One Time Key In     | Main         |         |                 | RETAINER, RR BUMPER, RH         | 1   | 112.70                  | 112.70         | 25.00  | 84.53           | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |
| One Time Key In     | Main         |         |                 | SEAL, RR BUMPER, LH             | 1   | 85.20                   | 85.20          | 25.00  | 63.90           | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |
| One Time Key In     | Main         |         |                 | SEAL, RR BUMPER, RH             | 1   | 85.20                   | 85.20          | 25.00  | 63.90           | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |
| One Time Key In     | Main         |         |                 | GUARD, RR BUMPER, LOWER         | 1   | 558.30                  | 558.30         | 25.00  | 418.72          | Replace         | 1                 | 418.72                   | Replace        | ✓ /SCR   |
| One Time Key In     | Main         |         |                 | COVER, GUARD RR BUMPER LOWER    | 1   | 14.80                   | 14.80          | 25.00  | 11.10           | Replace         | 1                 | 11.10                    | Replace        | ✓ /SCR   |
| One Time Key In     | Main         |         |                 | PAD, RR BUMPER, CTR             | 3   | 2.20                    | 6.60           | 25.00  | 4.95            | Replace         | 3                 | 4.95                     | Replace        | ✓ /Nec   |
| One Time Key In     | Main         |         |                 | LENS & BODY ASSY, RR BUMPER, RH | 1   | 486.80                  | 486.80         | 10.00  | 438.12          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |
| One Time Key In     | Main         |         |                 | LENS & BODY ASSY, RR BUMPER, LH | 1   | 486.80                  | 486.80         | 10.00  | 438.12          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |
| One Time Key In     | Main         |         |                 | WIRE, LUGGAGE ROOM              | 1   | 143.50                  | 143.50         | 10.00  | 129.15          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |
| One Time Key In     | Main         |         |                 | COVER, REAR FLOOR UNDER, LH     | 1   | 234.30                  | 234.30         | 25.00  | 175.73          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |
| One Time Key In     | Main         |         |                 | COVER, REAR FLOOR UNDER, RH     | 1   | 169.50                  | 169.50         | 25.00  | 127.13          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |
| One Time Key In     | Main         |         |                 | COVER, REAR FLOOR UNDER CENTER  | 1   | 222.60                  | 222.60         | 25.00  | 166.95          | Replace         | 0                 | 0                        | Not Give       | ✓ Xsuc   |

Total Spare Part Cost 10,281.91

Surveyor Total 1,494.12

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,225.53

Final Sur Total 1,195.30

| SMRT Recommendation |              |         |                 |                                                 |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|-------------------------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                                       | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | CLIP , FLOOR UNDER COVER , NO.1                 | 10  | 2.60                    | 26.00          | 25.00  | 19.50           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | CLIP , FLOOR UNDER COVER , NO.2                 | 10  | 3.20                    | 32.00          | 25.00  | 24.00           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE PANEL SUB-ASSY, BACK DOOR             | 1   | 929.60                  | 929.60         | 25.00  | 697.20          | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY    | 1   | 891.20                  | 891.20         | 25.00  | 668.40          | Replace         | 1                 | 0                        | Repair         | ✓ X R   |
| One Time Key In     | Main         |         |                 | TAIL GATE LOCK ASSY, BACK DOOR                  | 1   | 452.10                  | 452.10         | 10.00  | 406.89          | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE LOCK COVER , BACK DOOR                | 1   | 25.30                   | 25.30          | 25.00  | 18.98           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE STRIKER ASSY, BACK DOOR               | 1   | 24.90                   | 24.90          | 25.00  | 18.67           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE   | 1   | 27.90                   | 27.90          | 25.00  | 20.92           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE MOULDING GLASS, BACK DOOR             | 1   | 29.70                   | 29.70          | 25.00  | 22.27           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE   | 1   | 27.90                   | 27.90          | 25.00  | 20.92           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE MOULDING LOWER GLASS , BACK DOOR , LH | 1   | 29.90                   | 29.90          | 25.00  | 22.42           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE MOULDING LOWER GLASS , BACK DOOR , RH | 1   | 29.90                   | 29.90          | 25.00  | 22.42           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE MOULDING LOWER GLASS , BACK DOOR      | 1   | 19.70                   | 19.70          | 25.00  | 14.77           | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | SEALANT W/SCREEN                                | 3   | 37.00                   | 111.00         | 0.00   | 111.00          | Replace         | 0                 | 0                        | Not Give       | ✓ X SUC |
| One Time Key In     | Main         |         |                 | TAIL GATE WEATHERSTRIP, BACK DOOR               | 1   | 360.70                  | 360.70         | 25.00  | 270.52          | Replace         | 1                 | 270.52                   | Replace        | ✓ / BR  |

Total Spare Part Cost 10,281.91

Surveyor Total 1,494.12

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,225.53

Final Sur Total 1,195.30

| SMRT Recommendation |              |         |                 |                                                |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|------------------------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                                      | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | ANTENNA, ELECTRICAL KEY                        | 1   | 60.30                   | 60.30          | 10.00  | 54.27           | Replace         | 0                 | 0                        | Not Give       | ✓ X Suc |
| One Time Key In     | Main         |         |                 | NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR | 1   | 52.30                   | 52.30          | 25.00  | 39.22           | Replace         | 1                 | 39.22                    | Replace        | ✓ / Nec |
| One Time Key In     | Main         |         |                 | NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR  | 1   | 52.30                   | 52.30          | 25.00  | 39.22           | Replace         | 1                 | 39.22                    | Replace        | ✓ / Nec |
| One Time Key In     | Main         |         |                 | EMBLEM SUB- ASSY REAR                          | 1   | 46.30                   | 46.30          | 25.00  | 34.72           | Replace         | 1                 | 34.72                    | Replace        | ✓ / Nec |
| One Time Key In     | Main         |         |                 | SMRT LOGO                                      | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace         | 1                 | 7.80                     | Replace        | ✓ / Nec |
| One Time Key In     | Main         |         |                 | STICKER DECAL 6555 8888                        | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace         | 1                 | 21.60                    | Replace        | ✓ Nec   |
| One Time Key In     | Main         |         |                 | SPOILER SUB- ASSY, REAR                        | 1   | 1,322.10                | 1,322.10       | 25.00  | 991.57          | Replace         | 0                 | 0                        | Not Give       | ✓ X Suc |
| One Time Key In     | Main         |         |                 | LAMP SET, STOP CENTER                          | 1   | 186.50                  | 186.50         | 10.00  | 167.85          | Replace         | 0                 | 0                        | Not Give       | ✓ X Suc |
| One Time Key In     | Main         |         |                 | END PANEL SUBASSY, BODY LOWER BACK             | 1   | 629.80                  | 629.80         | 25.00  | 472.35          | Replace         | 1                 | 0                        | Repair         | ✓ X R   |
| One Time Key In     | Main         |         |                 | END PANEL , COVER, DECK TRIM SERVICE HOLE      | 1   | 47.00                   | 47.00          | 25.00  | 35.25           | Replace         | 0                 | 0                        | Not Give       | ✓ X Suc |
| One Time Key In     | Main         |         |                 | END PANEL , COVER, DECK TRIM, REAR             | 1   | 122.80                  | 122.80         | 25.00  | 92.10           | Replace         | 0                 | 0                        | Not Give       | ✓ X Suc |
| One Time Key In     | Main         |         |                 | SEALANT SIKAFLEX                               | 1   | 37.00                   | 37.00          | 0.00   | 37.00           | Replace         | 0                 | 0                        | Not Give       | ✓ X Suc |
| One Time Key In     | Main         |         |                 | SPARE TYRE PANEL , PAN, REAR FLOOR             | 1   | 564.80                  | 564.80         | 25.00  | 423.60          | Replace         | 0                 | 0                        | Not Give       | ✓ X Suc |
| One Time Key In     | Main         |         |                 | BOARD, REAR FLOOR, NO.1                        | 1   | 502.20                  | 502.20         | 25.00  | 376.65          | Replace         | 0                 | 0                        | Not Give       | ✓ X Suc |
| One Time Key In     | Main         |         |                 | BOX, DECK FLOOR, LH                            | 1   | 303.40                  | 303.40         | 25.00  | 227.55          | Replace         | 0                 | 0                        | Not Give       | ✓ X Suc |

Total Spare Part Cost 10,281.91

Surveyor Total 1,494.12

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,225.53

Final Sur Total 1,195.30

| SMRT Recommendation   |              |         |                 |                                        |     |                         |                |        |                 |                          | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|----------------------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                              | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | BOX, DECK FLOOR, RH                    | 1   | 304.00                  | 304.00         | 25.00  | 228.00          | Replace                  | 0                 | 0                        | Not Give       | ✓ X sue |
| One Time Key In       | Main         |         |                 | PANEL ASSY, DECK TRIM SIDE, LH         | 1   | 344.70                  | 344.70         | 25.00  | 258.52          | Replace                  | 0                 | 0                        | Not Give       | ✓ X sue |
| One Time Key In       | Main         |         |                 | PANEL ASSY, DECK TRIM SIDE, RH         | 1   | 344.70                  | 344.70         | 25.00  | 258.52          | Replace                  | 0                 | 0                        | Not Give       | ✓ X sue |
| One Time Key In       | Main         |         |                 | LENS & BODY, REAR COMBINATION LAMP, RH | 1   | 438.10                  | 438.10         | 10.00  | 394.29          | Replace                  | 0                 | 0                        | Not Give       | ✓ X sue |
| One Time Key In       | Main         |         |                 | COVER, REAR COMBINATION LAMP, RH       | 1   | 54.00                   | 54.00          | 25.00  | 40.50           | Replace                  | 0                 | 0                        | Not Give       | ✓ X sue |
| One Time Key In       | Main         |         |                 | LENS & BODY, REAR COMBINATION LAMP, LH | 1   | 438.10                  | 438.10         | 10.00  | 394.29          | Replace                  | 0                 | 0                        | Not Give       | ✓ X sue |
| One Time Key In       | Main         |         |                 | COVER, REAR COMBINATION LAMP, LH       | 1   | 54.00                   | 54.00          | 25.00  | 40.50           | Replace                  | 0                 | 0                        | Not Give       | ✓ X sue |
| Total Spare Part Cost |              |         |                 |                                        |     |                         |                |        | 10,281.91       | Surveyor Total 1,494.12  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                                        |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20      |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                                        |     |                         |                |        | 8,225.53        | Final Sur Total 1,195.30 |                   |                          |                |         |

**Labour's Cost Detail**

| S.No.  | Costing Type | Job Scope              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR REAR PORTION | 1,014.00                | 400                     |         |
| Total: |              |                        | 1,014.00                | 400.00                  |         |

**Spray Cost Detail**

| S.No.  | Costing Type | Job Scope                      | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|--------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO RESPRAY REAR BUMPER         | 378.00                  | 200                     |         |
| 2      | Main         | TO RESPRAY FILLER RR BUMPER LH | 180.00                  | 0                       |         |
| 3      | Main         | TO RESPRAY FILLER RR BUMPER RH | 180.00                  | 0                       |         |
| 4      | Main         | TO RESPRAY BUMPER BEAM         | 180.00                  | 0                       |         |
| 5      | Main         | TO RESPRAY TAIL GATE           | 378.00                  | 0                       |         |
| Total: |              |                                | 2,016.00                | 400.00                  |         |

| S.No.         | Costing Type | Job Scope                           | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|---------------|--------------|-------------------------------------|----------------------------|----------------------------|---------|
| 6             | Main         | TO RESPRAY TAILGATE OUTSIDE GARNISH | 180.00                     | 100                        |         |
| 7             | Main         | TO RESPRAY REAR SPOILER             | 180.00                     | 0                          |         |
| 8             | Main         | TO RESPRAY REAR PANEL               | 180.00                     | 100                        |         |
| 9             | Main         | TO RESPRAY REAR SPARE TYRE PANEL    | 180.00                     | 0                          |         |
| <b>Total:</b> |              |                                     | <b>2,016.00</b>            | <b>400.00</b>              |         |

**Other Cost Detail**

| S.No.         | Costing Type | Job Scope                                                               | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|---------------|--------------|-------------------------------------------------------------------------|----------------------------|----------------------------|---------|
| 1             | Main         | TO CHECK WIRING AND SYSTEM FUNCTION                                     | 80.00                      | 20                         |         |
| 2             | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA                                 | 100.00                     | 30                         |         |
| 3             | Main         | TO TRANSFER REAR TAILGATE MECHANISM                                     | 120.00                     | 0                          |         |
| 4             | Main         | TO TEST AND REFIX REVERSE SENSOR SYSTEM                                 | 120.00                     | 30                         |         |
| 5             | Main         | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.    | 120.00                     | 0                          |         |
| 6             | Main         | TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE | 120.00                     | 0                          |         |
| 7             | Main         | TO REMOVE AND REFIX REAR WINDSCREEN                                     | 240.00                     | 0                          |         |
| 8             | Main         | TO REMOVE AND REFIT WIRE HARDESS                                        | 250.00                     | 0                          |         |
| 9             | Main         | TO REPLACE SUNDRY PARTS                                                 | 100.00                     | 0                          |         |
| 10            | Main         | TO WASH AND VACUUM                                                      | 60.00                      | 0                          |         |
| <b>Total:</b> |              |                                                                         | <b>1,310.00</b>            | <b>80.00</b>               |         |

**Summary**

|                         | Estimator Assesment(\$) | Surveyor Assesment(\$) |
|-------------------------|-------------------------|------------------------|
| Total Spare Part Detail | 8,225.53                | 1,195.30               |
| Total Labour Cost       | 1,014.00                | 400.00                 |
| Total Spray Painting    | 2,016.00                | 400.00                 |
| Other                   | 1,310.00                | 80.00                  |
| Overall Total           | 12,565.53               | 2,075.30               |

|                          | Estimator Assessment(\$)                                                          | Surveyor Assessment(\$)                                                             |
|--------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Lump Sum Repair Option   | <input type="checkbox"/>                                                          | <input checked="" type="checkbox"/>                                                 |
| Lump Sum Total           | 12,550.00                                                                         | 2,100.00                                                                            |
| Surveyor Approved Amount |                                                                                   | 2,100.00                                                                            |
| No of Repair Days*       | 7                                                                                 | 3 <i>3 days</i>                                                                     |
| Remarks                  | -                                                                                 | L/S, After paint photo.                                                             |
| Surveyor Name            |                                                                                   | Sun Pin (LKK)                                                                       |
| Signature                |  |  |
| Survey Date              | 20/10/2020                                                                        |                                                                                     |

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: