

SHC4470P

Section A - Accident Details

Registration Number	SHC4470P
Case Reference Number	TAX/10/20/2037
Registration Date	12/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	ONG ENG JOO
Type of Accident	Head to Rear
Accident Date and Time	20/10/2020 7 42 AM
Accident Reported Date and Time	20/10/2020 11 21 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108540
Special Instruction to ARC, if any	REAR PORTION DAMAGED / CHINA TAIPING - LKK
Prepared Date and Time	20/10/2020 1 23 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$2,016.00	\$400.00
Total Spare Part Cost	\$8,911.19	\$1,881.01
Total Other Cost	\$1,310.00	\$80.00
TOTAL COST	\$13,251.19	\$2,761.01
Lump Sum Total	\$13,250.00	\$2,750.00 (L/S)
Number of Repair Days	7.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	22/10/2020 9:56 AM	22/10/2020 9:09 AM
Signature		
Remarks	Total number of repair days = 3 days SUP = 0 day	L/S. After paint photo



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 03/11/2020

User ID PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2011-0001	Invoice Number	
Quotation Date	02 11 2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$400.00 /
Total Labour	\$1,014.00	\$400.00 /

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00 /
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,016.00	\$400.00 /

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 /
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,310.00	\$80.00 /

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8149847020	COVER, REAR COMBINATION LAMP, LH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given X
		8156147151	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given X
		8149747020	COVER, REAR COMBINATION LAMP, RH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given X
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given X
		6473047240C2	PANEL ASSY, DECK TRIM SIDE, RH	0.00	\$344.70	0.00	\$0.00	Replace	Not Given X

Suc
Suc
3 Suc

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number: 63685562
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated: 03/11/2020
User ID: PohSuan

64740471 90C2	PANEL ASSY. DECK TRIM SIDE, LH	0.00	\$344.70	0.00	\$0.00	Replace	Not Given	X
64995470 50	BOX, DECK FLOOR, RH	0.00	\$304.00	0.00	\$0.00	Replace	Not Given	X
64997470 60	BOX, DECK FLOOR, LH	0.00	\$303.40	0.00	\$0.00	Replace	Not Given	X
58415471 10C2	BOARD, REAR FLOOR, NO 1	0.00	\$502.20	0.00	\$0.00	Replace	Not Given	X
58311471 30	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Not Given	X
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
64716471 30C0	END PANEL, COVER, DECK TRIM, REAR	0.00	\$122.80	0.00	\$0.00	Replace	Not Given	X
64718470 80C0	END PANEL, COVER, DECK TRIM SERVICE HOLE	0.00	\$47.00	0.00	\$0.00	Replace	Not Given	X
58307470 90	END PANEL SUBASSY, BODY LOWER BACK	1.00	\$629.80	100.00	\$0.00	Replace	Repair	X
81006470 30	LAMP SET, STOP CENTER	0.00	\$186.50	0.00	\$0.00	Replace	Not Given	X
76085479 16	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X
75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	X
75442471 30	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	X
75441470 90	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	X
89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
67881470 50	TAIL GATE WEATHERSTRIP, BACK DOOR	1.00	\$360.70	25.00	\$270.53	Replace	Replace	X
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
75575470 51	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$19.70	0.00	\$0.00	Replace	Not Given	X
75573471 10	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X
75574470 40	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X
56117501 40	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	X
75571470 10	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$29.70	0.00	\$0.00	Replace	Not Given	X
56117501 40	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	X
69430520 50	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	X
69321470 10	TAIL GATE LOCK COVER, BACK DOOR	0.00	\$25.30	0.00	\$0.00	Replace	Not Given	X
69350470 50	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$452.10	0.00	\$0.00	Replace	Not Given	X
76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	X
67005474 40	TAIL GATE PANEL SUB- ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given	X
90467170 27C0	CLIP, FLOOR UNDER COVER, NO 2	0.00	\$3.20	0.00	\$0.00	Replace	Not Given	X
90467170 26A0	CLIP, FLOOR UNDER COVER, NO 1	0.00	\$2.60	0.00	\$0.00	Replace	Not Given	X
66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
82183470 20	WIRE, LUGGAGE ROOM	0.00	\$143.50	0.00	\$0.00	Replace	Not Given	X
81591470 10	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
81581470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace	X
52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	X
52453470 10	GUARD RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	X
52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X

Svc

SVC

NPC

NPC

NPC

NPC

NPC

Br

Svc

SVC

NPC

SCR

SCR

SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63665502
Estimator Telephone Number 68662023
Accident Reporting Number 68662672

Date Generated : 03/11/2020
User ID PohSuan

52592470	40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	✓
52575470	40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	✓
52576470	40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	✓
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
		SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	✓
52023470	30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	X
52565479	00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X
52566479	00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X
52191470	30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given	X
52462470	10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
52462470	20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
52462470	30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace	✓
52161160	10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	✓
52159479	13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	✓
Total				\$12,785.20		\$1,494.18			✓

SVC
NEC
Short
SVC
NEC
CRA

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52566479	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
		52565479	FILLER, RR BUMPER, RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
		52023470	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace
		81581470	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$486.80	10.00	\$438.12	Replace	Replace
Total					1,045.40		857.08		

Cut
Cut
BT
CRA

2351.26 ✓

- 202

1881.01 ✓

+ 400.00 ✓

+ 480.00 ✓

2761.01 ✓

4/2 \$2750/- ✓

3 days