



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2008005
INV Date 27/11/2020
Reference CC3/CTI20011475/Ees3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHD 4900K
Insured Veh. EM 9000M
Claim No. SNM20D204011
Policy No. DMHCSNW00002822000
Accident Date 21/10/2020
Inspection Date 21/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20011475/Ees3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-11-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EM 9000M	Veh. Inspected	SHD 4900K
Policy No.	DMHCSNW00002822000	Coverage (\$)	0.00
Claim No.	SNM20D204011	Excess (\$)	0.00
Assign From		Assign Date	21/10/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	KMHC851CVLU189453	Colour	BLUE
Odometer	115955	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	4 mm
L/H Front Tyre	195/65 R15	GOODYEAR	4 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	4 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/10/2020	Inspection Date	21/10/2020
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4900K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BROKEN	459.40	459.40
1	REAR BUMPER CTR MOULDING	BROKEN	451.25	451.25
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER BEAM	BROKEN	294.80	294.80
1	REAR BUMPER LWR MOULDING	NOT NECESSARY	155.00	-
1	REAR BUMPER SIDE BRKT RH	NOT NECESSARY	33.10	-
1	REAR BUMPER STAY RH	NOT NECESSARY	138.10	-
1	REAR BUMPER STAY LH	NOT NECESSARY	138.10	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	31.90	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	5.40	-
	LESS 20% DISCOUNT		-386.11	-245.49
			1,544.44	981.96
	<u>SPECIAL NETT ITEMS</u>			
1	NO PLATE (S) W/TRIM COVER (SN)	BROKEN	55.00	55.00
1	REVERSE SENSOR (SN)	BROKEN	135.70	135.70
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			240.70	240.70
	<u>LABOUR</u>			
	PANEL BEATING.		350.00	320.00
	SPRAYPAINT CHARGE.		250.00	200.00
	R/I REVERSE SENSOR.		120.00	30.00
			720.00	550.00
	GRAND TOTAL		2,505.14	1,772.66
	RECOMMENDED COST OF REPAIRS			1,772.66

Report Ref No. CC3/CTI20011475/Ees3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4900K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4900K

RE-INSPECTION

