



Section A - Accident Details

Registration Number	SHB5918P
Case Reference Number	TAX/10/20/2038
Registration Date	20/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAY KIM HONG
Type of Accident	Head to Rear
Accident Date and Time	20/10/2020 7:40 AM
Accident Reported Date and Time	20/10/2020 2:24 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108542
Special Instruction to ARC, if any	TP / REAR DAMAGE
Prepared Date and Time	21/10/2020 8:07 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$926.00	\$300.00
Total Spray Cost	\$1,098.00	\$300.00
Total Spare Part Cost	\$4,840.69	\$1,421.87
Total Other Cost	\$800.00	\$40.00
TOTAL COST	\$7,664.69	\$2,061.87 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	23/10/2020 1:22 PM	26/10/2020 10:53 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 1 day.	P/P, before paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2011-0063	Invoice Number	
Quotation Date	06.11.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$200.00
TO REPAIR REAR END PANEL	\$250.00	\$100.00
Total Labour	\$926.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$1,098.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$800.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace
		52462-47020	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52462-47130	PAD, RR BUMPER, RH & LH, 3	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.30	0.00	\$0.00	Replace	Not Given
		52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.50	0.00	\$0.00	Replace	Not Given
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace
		90467-06206-C0	CLIP SEAL, RR BUMPER, RH & LH	0.00	\$2.50	0.00	\$0.00	Replace	Not Given
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 06/11/2020
User ID PohSuan

75392-35220	RETAINER, OUTSIDE, RH & LH	0.00	\$3.90	0.00	\$0.00	Replace	Not Given	X	SVC
52169-47070	COVER, GUARD RR BUMPER LOWER	1.00	\$22.00	25.00	\$16.50	Replace	Replace	/	SCR
52461-47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace	/	Nec
81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$39.00	0.00	\$0.00	Replace	Check	X	SVC
81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	0.00	\$39.00	0.00	\$0.00	Replace	Not Given	X	SVC
52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Check	X	SVC
89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$72.00	0.00	\$0.00	Replace	Check	X	SVC
	REVERSE SENSOR, REAR BUMPER	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	SVC
58398-47050	COVER, REAR FLOOR UNDER, RH	1.00	\$175.10	25.00	\$131.33	Replace	Replace	/	Def
66259-47010	COVER, REAR FLOOR UNDER CENTER	1.00	\$229.90	25.00	\$172.43	Replace	Replace	/	Def
58399-47030	COVER, REAR FLOOR UNDER, LH	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	X	SVC
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	/	Nec
90467-17026-A0	CLIP, FLOOR UNDER COVER, NO.1	0.00	\$3.20	0.00	\$0.00	Replace	Not Given	X	SVC
90467-17027-C0	CLIP, FLOOR UNDER COVER, NO.2	0.00	\$3.90	0.00	\$0.00	Replace	Not Given	X	SVC
58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Check	X	SVC
64716-47130-C0	END PANEL, COVER, DECK TRIM, REAR	0.00	\$126.70	0.00	\$0.00	Replace	Check	X	SVC
64718-47080-C0	END PANEL, COVER, DECK TRIM SERVICE HOLE	0.00	\$48.50	0.00	\$0.00	Replace	Check	X	SVC
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	SVC
58311-47130	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$583.40	0.00	\$0.00	Replace	Not Given	X	SVC
17430-37B20	PIPE ASSY, EXHAUST, TAIL	0.00	\$1,649.00	0.00	\$0.00	Replace	Not Given	X	SVC
17565-22040	SUPPORT, EXHAUST PIPE NO 5	0.00	\$49.10	0.00	\$0.00	Replace	Not Given	X	SVC
17575-37030	BRACKET, EXHAUST PIPE SUPPORT	0.00	\$41.80	0.00	\$0.00	Replace	Not Given	X	SVC
Total			\$5,767.20		\$1,172.34				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$332.70	25.00	\$249.53	Replace	Replace
Total					332.70		249.53		

BT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1421.87 /
+ 300.00 /
+ 340.00 /
2061.87 /

P/P
\$2,061.87
4 days