

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 8608 0808

Email: auburnauto.claim@gmail.com

Vehicle No: SJN6835B

Model: Toyota Wish

		Repairer's Estimate	
QTY	Description		
	Spare Parts - List Items		
1	Front bumper side grille X N/M	\$	180.00
1	Front bonnet lock X N/M	\$	380.00
1	Front bonnet inner rubber X N/M	\$	68.20
1	Front bonnet outer rubber X N/M	\$	86.20
1	Front bumper inner sponge X N/M	\$	135.90
1	Front bumper side retainers / BR (LH & RH)	\$	145.20 ✓
1	Front headlamp lower bracket X N/M	\$	186.00
1	Front grille chrome moulding (Bonnet garnish) / CUT	\$	285.90 232 ✓
1	Front grille logo / MC	\$	188.80 53.90 ✓
1	Front grille / BR	\$	628.60 117.20 ✓
2	Front bumper reinforcement (Front Bumper) ? / BR	\$	680.60 ✓
1	Front bonnet lock X N/M	\$	380.00
1	Chrome "Toyota" logo X N/M	\$	135.00
1	L/H Headlight / CUT	\$	1,220.00 ✓
1	Bonnet / PD	\$	950.00 798 ✓
		\$	5,650.40

3246.90
- 25%
2435.17

c/f: \$ 5,650.40

S/N.	Labour Charges		
1	To check wiring and reset headlamps focussing.	\$ 30	320.00
2	To apply tuff kote.	\$ 30	330.00
3	Panel beating.	\$ 400	2,800.00
4	To sand-down, patch-work, re-spray paint.	\$ 400	2,200.00
		\$	5,650.00

Total Repair Cost: \$ 860 11,300.40

P-2435-17
L-860
3295-17
L/S-2636-13
= 2650

Survey:

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name) Steve
(Contact) 83228813
(Email) _____
(Signature) [Signature]
(Date/Time) 23/10/10, 1.30 pm

W1 ArL
3 dys
L/S

LKK Auto Consultants herice notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: